

## PROJECT TITLE :

|  | Company |     | Client    |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

-----  
: MIDAS/Civil Text (MCT) File.  
: Date : 2016/1/24  
-----

## \*VERSION

8.4.5

## \*UNIT : Unit System

: FORCE, LENGTH, HEAT, TEMPER

KN , MM, KCAL, C

## \*PROJINFO : Project Information

USER=g60

ADDRESS=e

## \*REBAR-MATL-CODE : Rebar Material Code

: CONC\_CODE, CONC\_MDB, SRC\_CODE, SRC\_MDB

KS01-Civil(RC), SD300, KS01-Civil(RC), SD300

## \*NODE : Nodes

: iNO, X, Y, Z

347, -9.22488979995e-005, 13199.871148, 0  
348, 385478.999893869, 13199.871148, 0  
349, -1.78209738806e-005, 2549.9999939755, 0  
362, 83501.7503297873, 4485.22677083008, 0  
371, 133501.877272276, 6148.31009043746, 0  
374, 385478.999893869, 6149.59835364601, 0  
375, 49.9998690832872, 9183.87113700001, 0  
376, 23276.3822133595, 9183.87113700001, 0  
377, 49.999848916661, 6566.00001000002, 0  
378, 23277.765525913, 6566.00050312739, 0  
379, 41501.99989, 9362.98883109866, 0  
380, 46486.0567467158, 9418.13240094975, 0  
381, 51486.1336807511, 9473.57898168599, 0  
382, 56486.2106379346, 9529.02556267891, 0  
383, 60486.3817120069, 9573.32539563099, 0  
384, 64486.6425469407, 9617.68491438456, 0  
385, 68486.903380679, 9662.04443312486, 0  
386, 73486.9796440895, 9717.49106171445, 0  
387, 78487.0566958414, 9772.93764375607, 0  
388, 83501.99989, 9828.54918935894, 0  
389, 27801.678580972, 6654.98310251546, 0  
390, 32355.60778739, 6744.67505848475, 0  
391, 36909.5300986326, 6834.36687865008, 0

## PROJECT TITLE :

|  | Company |     | Client    |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

392, 41501.9998898124, 6924.6991535, 0  
393, 46469.9268486154, 7034.81153712606, 0  
394, 51470.0797155623, 7145.77210589099, 0  
395, 56470.2325754607, 7256.73267449951, 0  
396, 60470.7546275882, 7345.51000072788, 0  
397, 64471.2766788853, 7434.28732693785, 0  
398, 68471.798728573, 7523.06465311209, 0  
399, 73471.9515668544, 7634.02522124091, 0  
400, 78472.1043953904, 7744.98578915343, 0  
401, 83501.99989, 7856.60638938317, 0  
402, 83507.99989, 8842.94095799996, 0  
403, 88478.3119709999, 8925.55931399998, 0  
404, 93478.4267965, 9008.79719499999, 0  
405, 98478.5405735, 9092.035347, 0  
406, 103478.6564615, 9175.27363099999, 0  
407, 108478.771301, 9258.51200349999, 0  
408, 113478.886145, 9341.75049199998, 0  
409, 118479.0009945, 9424.98910999997, 0  
410, 123479.1158505, 9508.22787049999, 0  
411, 128479.2307085, 9591.46627249998, 0  
412, 133501.99989, 9674.147153, 0  
413, 385478.999893869, 9674.73488562432, 0  
415, 499.999885999947, 13199.871148, 0  
416, 499.999885999947, 9183.87113700001, 0  
417, 499.999885999947, 6566.00001955355, 0  
418, 499.999885999947, 2550.00002108481, 0  
421, 5055.14788599999, 13199.871148, 0  
422, 5055.14788599999, 9183.87113700001, 0  
423, 5055.14788599999, 6566.00011625972, 0  
424, 5055.14788599999, 2550.00021866219, 0  
427, 9611.08648349997, 13199.871148, 0  
428, 9611.08648349997, 9183.87113700001, 0  
429, 9611.08648349997, 6566.00021298267, 0  
430, 9611.08648349997, 2550.00041627387, 0  
433, 14164.616807244, 13199.871148, 0  
434, 14165.7157056805, 9183.87113700001, 0  
435, 14166.4320339054, 6566.00030969303, 0  
436, 14167.5309322557, 2550.00061366161, 0  
439, 18719.4384603747, 13199.871148, 0  
440, 18721.0489594322, 9183.87113700001, 0  
441, 18722.0987797341, 6566.00040641021, 0  
442, 18723.7092786249, 2550.00081100267, 0  
445, 23279.8876256243, 2550.00100825117, 0  
446, 23274.2601133754, 13199.871148, 0  
449, 27837.7065353542, 13199.871148, 0

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

450, 27815.8450532677, 9228.4840621012, 0  
 451, 27779.5223931153, 2630.05932392946, 0  
 454, 32332.5657933118, 2781.6443954549, 0  
 455, 32370.3094856902, 9273.24441982753, 0  
 456, 32393.1398190706, 13199.871148, 0  
 459, 36948.5907004669, 13199.871148, 0  
 460, 36924.7704292687, 9318.00474326621, 0  
 461, 36885.591571281, 2933.22887984316, 0  
 464, 41501.9998899251, 3086.92356761627, 0  
 465, 41501.99989, 13199.871148, 0  
 468, 46511.4585000734, 13199.871148, 0  
 469, 46444.4616570983, 3251.47359584554, 0  
 472, 51444.5123560969, 3417.94094003603, 0  
 473, 51511.637748826, 13199.871148, 0  
 476, 56511.8257501269, 13199.871148, 0  
 477, 56444.5543148118, 3584.40799320998, 0  
 480, 60511.8202363068, 13199.871148, 0  
 481, 60445.3065728365, 3717.60556306789, 0  
 484, 64446.057567266, 3850.80309085676, 0  
 485, 64511.8525235618, 13199.871148, 0  
 488, 68511.886151868, 13199.871148, 0  
 489, 68446.8072194815, 3984.00057397416, 0  
 492, 73446.8245959253, 4150.46680865476, 0  
 493, 73512.0981156397, 13199.871148, 0  
 496, 78512.3220248928, 13199.871148, 0  
 497, 78446.8303532901, 4316.93265649984, 0  
 500, 83501.99989, 13199.871148, 0  
 503, 88513.5376376306, 13199.871148, 0  
 504, 88443.0738715655, 4649.73890382781, 0  
 507, 93513.8241306965, 13199.871148, 0  
 508, 93443.0166194057, 4816.20265400889, 0  
 511, 98514.1278323477, 13199.871148, 0  
 512, 98442.9413285187, 4982.66580324184, 0  
 515, 103442.847530023, 5149.12833629578, 0  
 516, 103514.451627376, 13199.871148, 0  
 519, 108514.796201773, 13199.871148, 0  
 520, 108442.732116533, 5315.59014972681, 0  
 523, 113515.164110397, 13199.871148, 0  
 524, 113442.593335264, 5482.05118573822, 0  
 527, 118442.428729075, 5648.51136136606, 0  
 528, 118515.557806782, 13199.871148, 0  
 531, 123515.980100275, 13199.871148, 0  
 532, 123442.235483667, 5814.97058352779, 0  
 535, 128516.434224263, 13199.871148, 0  
 536, 128442.010359897, 5981.42874482561, 0

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

539, 133501.99989, 13199.871148, 0  
 542, 138501.08161288, 6149.77681179529, 0  
 543, 138501.654410394, 9674.1588146202, 0  
 544, 138502.22742412, 13199.871148, 0  
 547, 143502.227423807, 13199.871148, 0  
 548, 143501.654412584, 9674.17047704622, 0  
 549, 143501.081613193, 6149.77319895916, 0  
 552, 148502.227423493, 13199.871148, 0  
 553, 148501.654414773, 9674.18213947225, 0  
 554, 148501.081613507, 6149.76958612303, 0  
 557, 153501.08161382, 6149.7659732869, 0  
 558, 153501.654416962, 9674.19380189827, 0  
 559, 153502.22742318, 13199.871148, 0  
 562, 158502.227422866, 13199.871148, 0  
 563, 158501.654419151, 9674.2054643243, 0  
 564, 158501.081614133, 6149.76236045077, 0  
 567, 163502.227423087, 13199.871148, 0  
 568, 163501.65442084, 9674.21712675033, 0  
 569, 163501.081612913, 6149.75874761464, 0  
 572, 168502.227422773, 13199.871148, 0  
 573, 168501.654423029, 9674.22878917635, 0  
 574, 168501.081613227, 6149.75513477851, 0  
 577, 173501.899255404, 13199.871148, 0  
 578, 173501.899255404, 9674.24045217344, 0  
 579, 173501.899255404, 6149.75152135158, 0  
 582, 178502.227422147, 13199.871148, 0  
 583, 178501.654427407, 9674.2521140284, 0  
 584, 178501.081613853, 6149.74790910625, 0  
 588, 183649.996827596, 6149.74418866887, 0  
 590, 188612.227421569, 13199.871148, 0  
 591, 188611.654433541, 9674.27569545383, 0  
 592, 188611.081617845, 6149.74060395159, 0  
 595, 193575.227422441, 13199.871148, 0  
 596, 193574.654436022, 9674.28727157791, 0  
 597, 193574.081617591, 6149.73701785045, 0  
 600, 198538.227423024, 13199.871148, 0  
 601, 198537.654438487, 9674.29884770198, 0  
 602, 198537.081617591, 6149.73343174931, 0  
 605, 203490.455171048, 13199.871148, 0  
 606, 203490.455171048, 9674.31040003641, 0  
 607, 203490.455171048, 6149.72985260392, 0  
 610, 208489.983640392, 13199.871148, 0  
 611, 208489.983640392, 9674.32206136259, 0  
 612, 208489.983640392, 6149.72624010851, 0  
 615, 213489.876459049, 13199.871148, 0

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

616, 213489.876459049, 9674.33372353862, 0  
617, 213489.876459049, 6149.72262734982, 0  
620, 218490.227423478, 13199.871148, 0  
621, 218489.654447777, 9674.3453854468, 0  
622, 218489.081618248, 6149.71901508802, 0  
625, 223490.227423241, 13199.871148, 0  
626, 223489.654449992, 9674.35704787283, 0  
627, 223489.081618535, 6149.71540225189, 0  
630, 228490.227423005, 13199.871148, 0  
631, 228489.654452206, 9674.36871029885, 0  
632, 228489.081618821, 6149.71178941576, 0  
635, 233490.227422769, 13199.871148, 0  
636, 233489.65445442, 9674.38037272488, 0  
637, 233489.081619108, 6149.70817657963, 0  
640, 238490.227422533, 13199.871148, 0  
641, 238489.654456634, 9674.3920351509, 0  
642, 238489.081619394, 6149.7045637435, 0  
645, 243490.227421999, 13199.871148, 0  
646, 243489.654458751, 9674.40369757693, 0  
647, 243489.081619784, 6149.70095090737, 0  
650, 248490.227421686, 13199.871148, 0  
651, 248489.65446094, 9674.41536000296, 0  
652, 248489.081620098, 6149.69733807124, 0  
655, 253649.304703, 13199.871148, 0  
656, 253649.304703, 9674.42739481081, 0  
657, 253649.304703, 6149.69360946316, 0  
660, 258612.118602055, 13199.871148, 0  
661, 258612.118602055, 9674.4389705008, 0  
662, 258612.118602055, 6149.69002349649, 0  
665, 263575.621646604, 13199.871148, 0  
666, 263575.048691577, 9674.4505464618, 0  
667, 263574.475843245, 6149.68643785978, 0  
670, 268537.475842662, 6149.68285175864, 0  
671, 268538.048693459, 9674.46212258587, 0  
672, 268538.621646604, 13199.871148, 0  
675, 273502.304703, 13199.871148, 0  
676, 273502.304703, 9674.47370163956, 0  
677, 273502.304703, 6149.67926433602, 0  
680, 278501.898025505, 13199.871148, 0  
681, 278502.154542577, 9674.48536371534, 0  
682, 278502.411017732, 6149.67565142307, 0  
685, 283502.411017592, 6149.67203858694, 0  
686, 283502.154541597, 9674.49702614136, 0  
687, 283501.898025645, 13199.871148, 0  
690, 288501.898025786, 13199.871148, 0

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

691, 288502.154540617, 9674.50868856738, 0  
692, 288502.411017452, 6149.66842575082, 0  
695, 293502.411017311, 6149.66481291469, 0  
696, 293502.154539637, 9674.5203509934, 0  
697, 293501.898025926, 13199.871148, 0  
700, 298501.849055773, 13199.871148, 0  
701, 298501.849055773, 9674.53201270688, 0  
702, 298501.849055773, 6149.66120048461, 0  
705, 303502.030453369, 13199.871148, 0  
706, 303502.030453369, 9674.54367555601, 0  
707, 303502.030453369, 6149.65758751741, 0  
710, 308502.030453369, 13199.871148, 0  
711, 308502.030453369, 9674.55533798203, 0  
712, 308502.030453369, 6149.65397468128, 0  
715, 313501.89802572, 13199.871148, 0  
716, 313502.154535467, 9674.56700069747, 0  
717, 313502.411017017, 6149.65036157017, 0  
720, 318501.898025594, 13199.871148, 0  
721, 318502.154534736, 9674.57866312349, 0  
722, 318502.411017643, 6149.64674873404, 0  
725, 323502.411017503, 6149.64313589791, 0  
726, 323502.154533756, 9674.59032554951, 0  
727, 323501.898025734, 13199.871148, 0  
730, 328648.999893869, 13199.871148, 0  
731, 328648.999893869, 9674.60233049016, 0  
732, 328648.999893869, 6149.63941714146, 0  
735, 338889.09434804, 13199.871148, 0  
736, 338889.09434804, 9674.62621535896, 0  
737, 338889.09434804, 6149.63201798482, 0  
740, 344008.898026043, 13199.871148, 0  
741, 344009.154529987, 9674.63815782358, 0  
742, 344009.411017695, 6149.62831821181, 0  
745, 349128.898026186, 13199.871148, 0  
746, 349129.154528983, 9674.65010014783, 0  
747, 349129.411017551, 6149.62461866761, 0  
750, 354248.89802633, 13199.871148, 0  
751, 354249.15452798, 9674.66204247207, 0  
752, 354249.411017407, 6149.62091912341, 0  
755, 359368.898026474, 13199.871148, 0  
756, 359369.154526976, 9674.67398479631, 0  
757, 359369.411017264, 6149.61721957922, 0  
760, 364488.898026617, 13199.871148, 0  
761, 364489.154525973, 9674.68592712056, 0  
762, 364489.41101712, 6149.61352003502, 0  
765, 369608.898026761, 13199.871148, 0

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

766, 369609.154524969, 9674.6978694448, 0  
 767, 369609.411016976, 6149.60982049082, 0  
 770, 374728.898026905, 13199.871148, 0  
 771, 374729.154523966, 9674.70981176904, 0  
 772, 374729.411016833, 6149.60612094663, 0  
 775, 379853.898027048, 13199.871148, 0  
 776, 379854.154522961, 9674.72176575571, 0  
 777, 379854.411016689, 6149.60241778959, 0  
 780, 384978.999893869, 13199.871148, 0  
 781, 384978.999893869, 9674.73371938172, 0  
 782, 384978.999893869, 6149.59871492962, 0  
 785, 333769.053823314, 6149.6357175583, 0  
 786, 333769.038072865, 9674.61427290346, 0  
 787, 333769.022321172, 13199.871148, 0  
 790, 183649.996827596, 13199.871148, 0  
 791, 183649.996827596, 9674.26412246088, 0  
 792, 385478.999893869, 15739.871149, 1235  
 793, 385478.999893869, 3599.59835300007, 1235  
 794, 499.999885999947, 15739.871148, 1235  
 795, 499.999885999947, 2.16538610402e-005, 1235  
 796, 5055.14788599999, 15739.871148, 1235  
 797, 5055.14788599999, 0.0002189269289374, 1235  
 798, 9611.08648349997, 15739.871148, 1235  
 799, 9611.08648349997, 0.0004162342374912, 1235  
 800, 14163.9217868204, 15739.871148, 1235  
 801, 14168.2286889802, 0.0006135936710052, 1235  
 802, 18718.4198678462, 15739.871148, 1235  
 803, 18724.7318813603, 0.0008109254413284, 1235  
 804, 23281.2350745647, 0.0010082571970997, 1235  
 805, 23272.9179485486, 15739.871148, 1235  
 806, 27851.6885933351, 15739.871148, 1235  
 807, 27765.474935862, 78.1787796404242, 1235  
 808, 32317.7284056214, 229.737551939645, 1235  
 809, 32407.9079777984, 15739.871148, 1235  
 810, 36964.1768857023, 15739.871148, 1235  
 811, 36869.9321542269, 381.294668865972, 1235  
 812, 41501.99989, 535.510708000031, 1235  
 813, 41501.99989, 15739.871148, 1235  
 814, 46528.5195552768, 15739.871148, 1235  
 815, 46427.2845555174, 699.488856636803, 1235  
 816, 51427.0094742363, 865.945354391049, 1235  
 817, 51529.0224116541, 15739.871148, 1235  
 818, 56529.5498367047, 15739.871148, 1235  
 819, 56426.7097325274, 1032.40103112243, 1235  
 820, 60529.6371497373, 15739.871148, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

821, 60427.4054230296, 1165.59671769473, 1235  
 822, 64428.0975481583, 1298.79228556882, 1235  
 823, 64529.7280153541, 15739.871148, 1235  
 824, 68529.8226546801, 15739.871148, 1235  
 825, 68428.7858864875, 1431.98772737307, 1235  
 826, 73428.4167874942, 1598.44109499427, 1235  
 827, 73530.4191823115, 15739.871148, 1235  
 828, 78531.0483689292, 15739.871148, 1235  
 829, 78428.0149073675, 1764.89337122888, 1235  
 830, 83501.99989, 1933.82221904612, 1235  
 831, 83501.99989, 15739.871148, 1235  
 832, 88534.470409201, 15739.871148, 1235  
 833, 88422.0412727654, 2097.62580262552, 1235  
 834, 93535.276681968, 15739.871148, 1235  
 835, 93421.4616152516, 2264.07216036093, 1235  
 836, 98536.1325184774, 15739.871148, 1235  
 837, 98420.8322009573, 2430.5168605401, 1235  
 838, 103420.148292061, 2596.95974743139, 1235  
 839, 103537.042637022, 15739.871148, 1235  
 840, 108538.012367721, 15739.871148, 1235  
 841, 108419.404535646, 2763.40064179248, 1235  
 842, 113539.047767837, 15739.871148, 1235  
 843, 113418.594849484, 2929.83934028332, 1235  
 844, 118417.712300328, 3096.27561370666, 1235  
 845, 118540.155741833, 15739.871148, 1235  
 846, 123541.344196259, 15739.871148, 1235  
 847, 123416.748947292, 3262.70919700891, 1235  
 848, 128542.622230681, 15739.871148, 1235  
 849, 128415.695651515, 3429.1397858615, 1235  
 850, 133501.99989, 15739.871148, 1235  
 851, 133501.99989, 3597.86894002854, 1235  
 852, 138500.667176553, 3599.7798301811, 1235  
 853, 138502.640235695, 15739.871148, 1235  
 854, 143502.640234945, 15739.871148, 1235  
 855, 143500.667177814, 3599.77934893574, 1235  
 856, 148502.640234194, 15739.871148, 1235  
 857, 148500.667179076, 3599.77886769039, 1235  
 858, 153500.667180337, 3599.77838644503, 1235  
 859, 153502.640233443, 15739.871148, 1235  
 860, 158502.640232692, 15739.871148, 1235  
 861, 158500.667181598, 3599.77790519968, 1235  
 862, 163502.64023322, 15739.871148, 1235  
 863, 163500.667180578, 3599.77742395432, 1235  
 864, 168502.64023247, 15739.871148, 1235  
 865, 168500.66718184, 3599.77694270897, 1235

## PROJECT TITLE :

|  | Company |     | Client    |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|                                                                                   | Author  | g60 | File Name | 노면교 (부산) |

866, 173501.899255404, 15739.871148, 1235  
867, 173501.899255404, 3599.77646134503, 1235  
868, 178502.640230968, 15739.871148, 1235  
869, 178500.667184363, 3599.77598021826, 1235  
870, 183649.996827596, 3599.77548460006, 1235  
871, 183649.996827596, 15739.871148, 1235  
872, 188612.640228317, 15739.871148, 1235  
873, 188610.667191466, 3599.77500714015, 1235  
874, 193575.640229384, 15739.871148, 1235  
875, 193573.66719152, 3599.77452945602, 1235  
876, 198538.640229967, 15739.871148, 1235  
877, 198536.667192025, 3599.77405177186, 1235  
878, 203490.455171048, 15739.871148, 1235  
879, 203490.455171048, 3599.77357497437, 1235  
880, 208489.983640392, 15739.871148, 1235  
881, 208489.983640392, 3599.77309377441, 1235  
882, 213489.876459049, 15739.871148, 1235  
883, 213489.876459049, 3599.77261253937, 1235  
884, 218490.640229503, 15739.871148, 1235  
885, 218488.667195634, 3599.7721314104, 1235  
886, 223490.640228867, 15739.871148, 1235  
887, 223488.667196831, 3599.77165016504, 1235  
888, 228490.640228231, 15739.871148, 1235  
889, 228488.667198028, 3599.77116891969, 1235  
890, 233490.640227595, 15739.871148, 1235  
891, 233488.667199225, 3599.77068767433, 1235  
892, 238490.640226959, 15739.871148, 1235  
893, 238488.667200422, 3599.77020642898, 1235  
894, 243490.640225881, 15739.871148, 1235  
895, 243488.667201868, 3599.76972518362, 1235  
896, 248490.64022513, 15739.871148, 1235  
897, 248488.667203129, 3599.76924393827, 1235  
898, 253649.304703, 15739.871148, 1235  
899, 253649.304703, 3599.76874723171, 1235  
900, 258612.118602055, 15739.871148, 1235  
901, 258612.118602055, 3599.76826956548, 1235  
902, 263576.034450049, 15739.871148, 1235  
903, 263574.061427812, 3599.76779198309, 1235  
904, 268537.061427734, 3599.76731429895, 1235  
905, 268539.034450049, 15739.871148, 1235  
906, 273502.304703, 15739.871148, 1235  
907, 273502.304703, 3599.76683639889, 1235  
908, 278501.713207898, 15739.871148, 1235  
909, 278502.596556367, 3599.76635512545, 1235  
910, 283502.596555802, 3599.7658738801, 1235

## PROJECT TITLE :

|  | Company |     | Client    |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|                                                                                     | Author  | g60 | File Name | 노면교 (부산) |

911, 283501.713208235, 15739.871148, 1235  
912, 288501.713208571, 15739.871148, 1235  
913, 288502.596555238, 3599.76539263474, 1235  
914, 293502.596554673, 3599.76491138939, 1235  
915, 293501.713208907, 15739.871148, 1235  
916, 298501.849055773, 15739.871148, 1235  
917, 298501.849055773, 3599.76443021598, 1235  
918, 303502.030453369, 15739.871148, 1235  
919, 303502.030453369, 3599.76394895316, 1235  
920, 308502.030453369, 15739.871148, 1235  
921, 308502.030453369, 3599.7634677078, 1235  
922, 313501.713209112, 15739.871148, 1235  
923, 313502.596553055, 3599.76298640796, 1235  
924, 318501.713208809, 15739.871148, 1235  
925, 318502.596553631, 3599.76250516261, 1235  
926, 323502.596553066, 3599.76202391725, 1235  
927, 323501.713209145, 15739.871148, 1235  
928, 328648.999893869, 15739.871148, 1235  
929, 328648.999893869, 3599.76152858071, 1235  
930, 338889.09434804, 15739.871148, 1235  
931, 338889.09434804, 3599.76054298112, 1235  
932, 344008.713209884, 15739.871148, 1235  
933, 344009.596551891, 3599.76005013754, 1235  
934, 349128.713210228, 15739.871148, 1235  
935, 349129.596551312, 3599.7595573423, 1235  
936, 354248.713210572, 15739.871148, 1235  
937, 354249.596550734, 3599.75906454706, 1235  
938, 359368.713210917, 15739.871148, 1235  
939, 359369.596550156, 3599.75857175181, 1235  
940, 364488.713211261, 15739.871148, 1235  
941, 364489.596549578, 3599.75807895657, 1235  
942, 369608.713211605, 15739.871148, 1235  
943, 369609.596548999, 3599.75758616133, 1235  
944, 374728.713211949, 15739.871148, 1235  
945, 374729.596548421, 3599.75709336608, 1235  
946, 379853.713212293, 15739.871148, 1235  
947, 379854.596547842, 3599.75660008959, 1235  
948, 384978.999893869, 15739.871148, 1235  
949, 384978.999893869, 3599.75610687052, 1235  
950, -0.000110000022687, 15739.871148, 1235  
951, 0, 0, 1235  
952, 333769.065216765, 3599.76103577917, 1235  
953, 333769.010971844, 15739.871148, 1235  
954, -0.0001068551791832, 15289.871148, 1235  
955, 385478.999893869, 15289.871148, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

956, -3.1448435038e-006, 449.999999999956, 1235  
 957, 385478.999937181, 4049.75605874599, 1235  
 958, -9.22488979995e-005, 13199.871148, 1235  
 959, 385478.999893869, 13199.871148, 1235  
 960, -1.78209738806e-005, 2549.99999939755, 1235  
 961, 83501.7503297873, 4485.22677083008, 1235  
 962, 133501.877272276, 6148.31009043746, 1235  
 963, 385478.999893869, 6149.59835364601, 1235  
 964, 49.9998690832872, 9183.87113700001, 1235  
 965, 23276.3822133595, 9183.87113700001, 1235  
 966, 49.999848916661, 6566.00001000002, 1235  
 967, 23277.765525913, 6566.00050312739, 1235  
 968, 41501.99989, 9362.98883109866, 1235  
 969, 46486.0567467158, 9418.13240094975, 1235  
 970, 51486.1336807511, 9473.57898168599, 1235  
 971, 56486.2106379346, 9529.02556267891, 1235  
 972, 60486.3817120069, 9573.32539563099, 1235  
 973, 64486.6425469407, 9617.68491438456, 1235  
 974, 68486.903380679, 9662.04443312486, 1235  
 975, 73486.9796440895, 9717.49106171445, 1235  
 976, 78487.0566958414, 9772.93764375607, 1235  
 977, 83501.99989, 9828.54918935894, 1235  
 978, 27801.678580972, 6654.98310251546, 1235  
 979, 32355.60778739, 6744.67505848475, 1235  
 980, 36909.5300986326, 6834.36687865008, 1235  
 981, 41501.9998898124, 6924.6991535, 1235  
 982, 46469.9268486154, 7034.81153712606, 1235  
 983, 51470.0797155623, 7145.77210589099, 1235  
 984, 56470.2325754607, 7256.73267449951, 1235  
 985, 60470.7546275882, 7345.51000072788, 1235  
 986, 64471.2766788853, 7434.28732693785, 1235  
 987, 68471.798728573, 7523.06465311209, 1235  
 988, 73471.9515668544, 7634.02522124091, 1235  
 989, 78472.1043953904, 7744.98578915343, 1235  
 990, 83501.99989, 7856.60638938317, 1235  
 993, 93478.4267965, 9008.79719499999, 1235  
 994, 98478.5405735, 9092.035347, 1235  
 995, 103478.6564615, 9175.27363099999, 1235  
 996, 108478.771301, 9258.51200349999, 1235  
 997, 113478.886145, 9341.75049199998, 1235  
 998, 118479.0009945, 9424.98910999997, 1235  
 999, 123479.1158505, 9508.22787049999, 1235  
 1000, 128479.2307085, 9591.46627249998, 1235  
 1001, 133501.99989, 9674.147153, 1235  
 1002, 385478.999893869, 9674.73488562432, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1003, 499.999885999947, 15289.871148, 1235  
 1004, 499.999885999947, 13199.871148, 1235  
 1005, 499.999885999947, 9183.87113700001, 1235  
 1006, 499.999885999947, 6566.00001955355, 1235  
 1007, 499.999885999947, 2550.00002108481, 1235  
 1008, 499.999885999947, 450.000021653812, 1235  
 1009, 5055.14788599999, 15289.871148, 1235  
 1010, 5055.14788599999, 13199.871148, 1235  
 1011, 5055.14788599999, 9183.87113700001, 1235  
 1012, 5055.14788599999, 6566.00011625972, 1235  
 1013, 5055.14788599999, 2550.00021866219, 1235  
 1014, 5055.14788599999, 450.000218926892, 1235  
 1015, 9611.08648349997, 15289.871148, 1235  
 1016, 9611.08648349997, 13199.871148, 1235  
 1017, 9611.08648349997, 9183.87113700001, 1235  
 1018, 9611.08648349997, 6566.00021298267, 1235  
 1019, 9611.08648349997, 2550.00041627387, 1235  
 1020, 9611.08648349997, 450.00041623421, 1235  
 1021, 14164.04492036, 15289.871148, 1235  
 1022, 14164.616807244, 13199.871148, 1235  
 1023, 14165.7157056805, 9183.87113700001, 1235  
 1024, 14166.4320339054, 6566.00030969303, 1235  
 1025, 14167.5309322557, 2550.00061366161, 1235  
 1026, 14168.1055554406, 450.000613588322, 1235  
 1027, 18718.6003271524, 15289.871148, 1235  
 1028, 18719.4384603747, 13199.871148, 1235  
 1029, 18721.0489594322, 9183.87113700001, 1235  
 1030, 18722.0987797341, 6566.00040641021, 1235  
 1031, 18723.7092786249, 2550.00081100267, 1235  
 1032, 18724.5514220541, 450.000810917609, 1235  
 1033, 23280.9972894576, 450.001008246897, 1235  
 1034, 23279.8876256243, 2550.00100825117, 1235  
 1035, 23274.2601133754, 13199.871148, 1235  
 1036, 23273.1557336557, 15289.871148, 1235  
 1037, 27849.2114570786, 15289.871148, 1235  
 1038, 27837.7065353542, 13199.871148, 1235  
 1039, 27815.8450532677, 9228.4840621012, 1235  
 1040, 27779.5223931153, 2630.05932392946, 1235  
 1041, 27767.9538989064, 528.510640343239, 1235  
 1042, 32320.3467681547, 680.074053687945, 1235  
 1043, 32332.5657933118, 2781.6443954549, 1235  
 1044, 32370.3094856902, 9273.24441982753, 1235  
 1045, 32393.1398190706, 13199.871148, 1235  
 1046, 32405.2915717246, 15289.871148, 1235  
 1047, 36961.4155536724, 15289.871148, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1048, 36948.5907004669, 13199.871148, 1235  
1049, 36924.7704292687, 9318.00474326621, 1235  
1050, 36885.591571281, 2933.22887984316, 1235  
1051, 36872.6955807661, 831.636000249256, 1235  
1052, 41501.9998899868, 985.760036259697, 1235  
1053, 41501.9998899251, 3086.92356761627, 1235  
1054, 41501.99989, 13199.871148, 1235  
1055, 41501.99989, 15289.871148, 1235  
1056, 46525.4969273865, 15289.871148, 1235  
1057, 46511.4585000734, 13199.871148, 1235  
1058, 46444.4616570983, 3251.47359584554, 1235  
1059, 46430.3158087381, 1149.83910480813, 1235  
1060, 51430.0982180943, 1316.2975166057, 1235  
1061, 51444.5123560969, 3417.94094003603, 1235  
1062, 51511.637748826, 13199.871148, 1235  
1063, 51525.9424517043, 15289.871148, 1235  
1064, 56526.409742626, 15289.871148, 1235  
1065, 56511.8257501269, 13199.871148, 1235  
1066, 56444.5543148118, 3584.40799320998, 1235  
1067, 56429.85877646, 1482.75520091537, 1235  
1068, 60526.4806099563, 15289.871148, 1235  
1069, 60511.8202363068, 13199.871148, 1235  
1070, 60445.3065728365, 3717.60556306789, 1235  
1071, 60430.5644494662, 1615.9512198365, 1235  
1072, 64431.2669632951, 1749.14713358299, 1235  
1073, 64446.057567266, 3850.80309085676, 1235  
1074, 64511.8525235618, 13199.871148, 1235  
1075, 64526.5610975169, 15289.871148, 1235  
1076, 68526.644927804, 15289.871148, 1235  
1077, 68511.886151868, 13199.871148, 1235  
1078, 68446.8072194815, 3984.00057397416, 1235  
1079, 68431.9661217219, 1882.34293562216, 1235  
1080, 73431.6652242763, 2048.79857388643, 1235  
1081, 73446.8245959253, 4150.46680865476, 1235  
1082, 73512.0981156397, 13199.871148, 1235  
1083, 73527.1733240429, 15289.871148, 1235  
1084, 78527.7307095527, 15289.871148, 1235  
1085, 78512.3220248928, 13199.871148, 1235  
1086, 78446.8303532901, 4316.93265649984, 1235  
1087, 78431.3352801773, 2215.25324509666, 1235  
1088, 83501.9558499625, 2384.07008107551, 1235  
1089, 83501.99989, 13199.871148, 1235  
1090, 83501.99989, 15289.871148, 1235  
1091, 88530.7618473086, 15289.871148, 1235  
1092, 88513.5376376306, 13199.871148, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1093, 88443.0738715655, 4649.73890382781, 1235  
1094, 88425.7529078478, 2547.99870284093, 1235  
1095, 93531.4760331207, 15289.871148, 1235  
1096, 93513.8241306965, 13199.871148, 1235  
1097, 93443.0166194057, 4816.20265400889, 1235  
1098, 93425.2654395142, 2714.44812984177, 1235  
1099, 98532.2340504623, 15289.871148, 1235  
1100, 98514.1278323477, 13199.871148, 1235  
1101, 98442.9413285187, 4982.66580324184, 1235  
1102, 98424.7338117027, 2880.89608564019, 1235  
1103, 103424.154039936, 3047.34243958159, 1235  
1104, 103442.847530023, 5149.12833629578, 1235  
1105, 103514.451627376, 13199.871148, 1235  
1106, 103533.040292793, 15289.871148, 1235  
1107, 108533.899267455, 15289.871148, 1235  
1108, 108514.796201773, 13199.871148, 1235  
1109, 108442.732116533, 5315.59014972681, 1235  
1110, 108423.521167568, 3213.78702562083, 1235  
1111, 113534.816411204, 15289.871148, 1235  
1112, 113515.164110397, 13199.871148, 1235  
1113, 113442.593335264, 5482.05118573822, 1235  
1114, 113422.829876385, 3380.22966581922, 1235  
1115, 118422.074023048, 3546.67015737405, 1235  
1116, 118442.428729075, 5648.51136136606, 1235  
1117, 118515.557806782, 13199.871148, 1235  
1118, 118535.797839954, 15289.871148, 1235  
1119, 123536.850557206, 15289.871148, 1235  
1120, 123515.980100275, 13199.871148, 1235  
1121, 123442.235483667, 5814.97058352779, 1235  
1122, 123421.246571358, 3713.10826525876, 1235  
1123, 128537.982623244, 15289.871148, 1235  
1124, 128516.434224263, 13199.871148, 1235  
1125, 128442.010359897, 5981.42874482561, 1235  
1126, 128420.339423583, 3879.54371983594, 1235  
1127, 133501.99989, 15289.871148, 1235  
1128, 133501.99989, 13199.871148, 1235  
1129, 133501.978255332, 4047.86870648561, 1235  
1130, 138500.740312462, 4049.77983017398, 1235  
1131, 138501.08161288, 6149.77681179529, 1235  
1132, 138501.654410394, 9674.1588146202, 1235  
1133, 138502.22742412, 13199.871148, 1235  
1134, 138502.567099786, 15289.871148, 1235  
1135, 143502.567099113, 15289.871148, 1235  
1136, 143502.227423807, 13199.871148, 1235  
1137, 143501.654412584, 9674.17047704622, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1138, 143501.081613193, 6149.77319895916, 1235  
 1139, 143500.740313646, 4049.77934892863, 1235  
 1140, 148502.56709844, 15289.871148, 1235  
 1141, 148502.227423493, 13199.871148, 1235  
 1142, 148501.654414773, 9674.18213947225, 1235  
 1143, 148501.081613507, 6149.76958612303, 1235  
 1144, 148500.74031483, 4049.77886768327, 1235  
 1145, 153500.740316013, 4049.77838643792, 1235  
 1146, 153501.08161382, 6149.7659732869, 1235  
 1147, 153501.654416962, 9674.19380189827, 1235  
 1148, 153502.22742318, 13199.871148, 1235  
 1149, 153502.567097767, 15289.871148, 1235  
 1150, 158502.567097093, 15289.871148, 1235  
 1151, 158502.227422866, 13199.871148, 1235  
 1152, 158501.654419151, 9674.2054643243, 1235  
 1153, 158501.081614133, 6149.76236045077, 1235  
 1154, 158500.740317197, 4049.77790519256, 1235  
 1155, 163502.567097567, 15289.871148, 1235  
 1156, 163502.227423087, 13199.871148, 1235  
 1157, 163501.65442084, 9674.21712675033, 1235  
 1158, 163501.081612913, 6149.75874761464, 1235  
 1159, 163500.740316232, 4049.77742394721, 1235  
 1160, 168502.567096894, 15289.871148, 1235  
 1161, 168502.227422773, 13199.871148, 1235  
 1162, 168501.654423029, 9674.22878917635, 1235  
 1163, 168501.081613227, 6149.75513477851, 1235  
 1164, 168500.740317416, 4049.77694270186, 1235  
 1165, 173501.899255404, 15289.871148, 1235  
 1166, 173501.899255404, 13199.871148, 1235  
 1167, 173501.899255404, 9674.24045217344, 1235  
 1168, 173501.899255404, 6149.75152135158, 1235  
 1169, 173501.899255404, 4049.77646134496, 1235  
 1170, 178502.567095547, 15289.871148, 1235  
 1171, 178502.227422147, 13199.871148, 1235  
 1172, 178501.654427407, 9674.2521140284, 1235  
 1173, 178501.081613853, 6149.74790910625, 1235  
 1174, 178500.740319784, 4049.77598021115, 1235  
 1175, 183649.996827596, 4049.77548459999, 1235  
 1176, 183649.996827596, 6149.74418866887, 1235  
 1177, 188612.567093263, 15289.871148, 1235  
 1178, 188612.227421569, 13199.871148, 1235  
 1179, 188611.654433541, 9674.27569545383, 1235  
 1180, 188611.081617845, 6149.74060395159, 1235  
 1181, 188610.74032652, 4049.77500713304, 1235  
 1182, 193575.567094295, 15289.871148, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1183, 193575.227422441, 13199.871148, 1235  
 1184, 193574.654436022, 9674.28727157791, 1235  
 1185, 193574.081617591, 6149.73701785045, 1235  
 1186, 193573.740326608, 4049.7745294489, 1235  
 1187, 198538.567094878, 15289.871148, 1235  
 1188, 198538.227423024, 13199.871148, 1235  
 1189, 198537.654438487, 9674.29884770198, 1235  
 1190, 198537.081617591, 6149.73343174931, 1235  
 1191, 198536.740327113, 4049.77405176476, 1235  
 1192, 203490.455171048, 15289.871148, 1235  
 1193, 203490.455171048, 13199.871148, 1235  
 1194, 203490.455171048, 9674.31040003641, 1235  
 1195, 203490.455171048, 6149.72985260392, 1235  
 1196, 203490.455171048, 4049.77357497431, 1235  
 1197, 208489.983640392, 15289.871148, 1235  
 1198, 208489.983640392, 13199.871148, 1235  
 1199, 208489.983640392, 9674.32206136259, 1235  
 1200, 208489.983640392, 6149.72624010851, 1235  
 1201, 208489.983640392, 4049.77309377434, 1235  
 1202, 213489.876459049, 15289.871148, 1235  
 1203, 213489.876459049, 13199.871148, 1235  
 1204, 213489.876459049, 9674.33372353862, 1235  
 1205, 213489.876459049, 6149.72262734982, 1235  
 1206, 213489.876459049, 4049.77261253931, 1235  
 1207, 218490.567094577, 15289.871148, 1235  
 1208, 218490.227423478, 13199.871148, 1235  
 1209, 218489.654447777, 9674.3453854468, 1235  
 1210, 218489.081618248, 6149.71901508802, 1235  
 1211, 218488.74033056, 4049.7721314033, 1235  
 1212, 223490.567094012, 15289.871148, 1235  
 1213, 223490.227423241, 13199.871148, 1235  
 1214, 223489.654449992, 9674.35704787283, 1235  
 1215, 223489.081618535, 6149.71540225189, 1235  
 1216, 223488.740331686, 4049.77165015795, 1235  
 1217, 228490.567093447, 15289.871148, 1235  
 1218, 228490.227423005, 13199.871148, 1235  
 1219, 228489.654452206, 9674.36871029885, 1235  
 1220, 228489.081618821, 6149.71178941576, 1235  
 1221, 228488.740332812, 4049.7711689126, 1235  
 1222, 233490.567092882, 15289.871148, 1235  
 1223, 233490.227422769, 13199.871148, 1235  
 1224, 233489.65445442, 9674.38037272488, 1235  
 1225, 233489.081619108, 6149.70817657963, 1235  
 1226, 233488.740333938, 4049.77068766724, 1235  
 1227, 238490.567092317, 15289.871148, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1228, 238490.227422533, 13199.871148, 1235  
 1229, 238489.654456634, 9674.3920351509, 1235  
 1230, 238489.081619394, 6149.7045637435, 1235  
 1231, 238488.740335064, 4049.77020642189, 1235  
 1232, 243490.567091335, 15289.871148, 1235  
 1233, 243490.227421999, 13199.871148, 1235  
 1234, 243489.654458751, 9674.40369757693, 1235  
 1235, 243489.081619784, 6149.70095090737, 1235  
 1236, 243488.740336414, 4049.76972517654, 1235  
 1237, 248490.567090661, 15289.871148, 1235  
 1238, 248490.227421686, 13199.871148, 1235  
 1239, 248489.65446094, 9674.41536000296, 1235  
 1240, 248489.081620098, 6149.69733807124, 1235  
 1241, 248488.740337598, 4049.76924393118, 1235  
 1242, 253649.304703, 15289.871148, 1235  
 1243, 253649.304703, 13199.871148, 1235  
 1244, 253649.304703, 9674.42739481081, 1235  
 1245, 253649.304703, 6149.69360946316, 1235  
 1246, 253649.304703, 4049.76874723166, 1235  
 1247, 258612.118602055, 15289.871148, 1235  
 1248, 258612.118602055, 13199.871148, 1235  
 1249, 258612.118602055, 9674.4389705008, 1235  
 1250, 258612.118602055, 6149.69002349649, 1235  
 1251, 258612.118602055, 4049.76826956543, 1235  
 1252, 263575.96131558, 15289.871148, 1235  
 1253, 263575.621646604, 13199.871148, 1235  
 1254, 263575.048691577, 9674.4505464618, 1235  
 1255, 263574.475843245, 6149.68643785978, 1235  
 1256, 263574.13456228, 4049.767791976, 1235  
 1257, 268537.134562202, 4049.76731429187, 1235  
 1258, 268537.475842662, 6149.68285175864, 1235  
 1259, 268538.048693459, 9674.46212258587, 1235  
 1260, 268538.621646604, 13199.871148, 1235  
 1261, 268538.96131558, 15289.871148, 1235  
 1262, 273502.304703, 15289.871148, 1235  
 1263, 273502.304703, 13199.871148, 1235  
 1264, 273502.304703, 9674.47370163956, 1235  
 1265, 273502.304703, 6149.67926433602, 1235  
 1266, 273502.304703, 4049.76683639885, 1235  
 1267, 278501.745951175, 15289.871148, 1235  
 1268, 278501.898025505, 13199.871148, 1235  
 1269, 278502.154542577, 9674.48536371534, 1235  
 1270, 278502.411017732, 6149.67565142307, 1235  
 1271, 278502.563813091, 4049.76635512856, 1235  
 1272, 283502.56381256, 4049.76587388321, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1273, 283502.411017592, 6149.67203858694, 1235  
 1274, 283502.154541597, 9674.49702614136, 1235  
 1275, 283501.898025645, 13199.871148, 1235  
 1276, 283501.745951477, 15289.871148, 1235  
 1277, 288501.745951778, 15289.871148, 1235  
 1278, 288501.898025786, 13199.871148, 1235  
 1279, 288502.154540617, 9674.50868856738, 1235  
 1280, 288502.411017452, 6149.66842575082, 1235  
 1281, 288502.563812031, 4049.76539263785, 1235  
 1282, 293502.5638115, 4049.7649113925, 1235  
 1283, 293502.411017311, 6149.66481291469, 1235  
 1284, 293502.154539637, 9674.5203509934, 1235  
 1285, 293501.898025926, 13199.871148, 1235  
 1286, 293501.745952079, 15289.871148, 1235  
 1287, 298501.849055773, 15289.871148, 1235  
 1288, 298501.849055773, 13199.871148, 1235  
 1289, 298501.849055773, 9674.53201270688, 1235  
 1290, 298501.849055773, 6149.66120048461, 1235  
 1291, 298501.849055773, 4049.76443021594, 1235  
 1292, 303502.030453369, 15289.871148, 1235  
 1293, 303502.030453369, 13199.871148, 1235  
 1294, 303502.030453369, 9674.54367555601, 1235  
 1295, 303502.030453369, 6149.65758751741, 1235  
 1296, 303502.030453369, 4049.76394895313, 1235  
 1297, 308502.030453369, 15289.871148, 1235  
 1298, 308502.030453369, 13199.871148, 1235  
 1299, 308502.030453369, 9674.55533798203, 1235  
 1300, 308502.030453369, 6149.65397468128, 1235  
 1301, 308502.030453369, 4049.76346770777, 1235  
 1302, 313501.745952212, 15289.871148, 1235  
 1303, 313501.89802572, 13199.871148, 1235  
 1304, 313502.154535467, 9674.56700069747, 1235  
 1305, 313502.411017017, 6149.65036157017, 1235  
 1306, 313502.563809955, 4049.76298641108, 1235  
 1307, 318501.74595194, 15289.871148, 1235  
 1308, 318501.898025594, 13199.871148, 1235  
 1309, 318502.154534736, 9674.57866312349, 1235  
 1310, 318502.411017643, 6149.64674873404, 1235  
 1311, 318502.5638105, 4049.76250516573, 1235  
 1312, 323502.56380997, 4049.76202392038, 1235  
 1313, 323502.411017503, 6149.64313589791, 1235  
 1314, 323502.154533756, 9674.59032554951, 1235  
 1315, 323501.898025734, 13199.871148, 1235  
 1316, 323501.745952241, 15289.871148, 1235  
 1317, 328648.999893869, 15289.871148, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1318, 328648.999893869, 13199.871148, 1235  
 1319, 328648.999893869, 9674.60233049016, 1235  
 1320, 328648.999893869, 6149.63941714146, 1235  
 1321, 328648.999893869, 4049.76152858069, 1235  
 1322, 338889.09434804, 15289.871148, 1235  
 1323, 338889.09434804, 13199.871148, 1235  
 1324, 338889.09434804, 9674.62621535896, 1235  
 1325, 338889.09434804, 6149.63201798482, 1235  
 1326, 338889.09434804, 4049.76054298111, 1235  
 1327, 344008.745952904, 15289.871148, 1235  
 1328, 344008.898026043, 13199.871148, 1235  
 1329, 344009.154529987, 9674.63815782358, 1235  
 1330, 344009.411017695, 6149.62831821181, 1235  
 1331, 344009.563808871, 4049.76005014068, 1235  
 1332, 349128.745953213, 15289.871148, 1235  
 1333, 349128.898026186, 13199.871148, 1235  
 1334, 349129.154528983, 9674.65010014783, 1235  
 1335, 349129.411017551, 6149.62461866761, 1235  
 1336, 349129.563808328, 4049.75955734544, 1235  
 1337, 354248.745953521, 15289.871148, 1235  
 1338, 354248.89802633, 13199.871148, 1235  
 1339, 354249.15452798, 9674.66204247207, 1235  
 1340, 354249.411017407, 6149.62091912341, 1235  
 1341, 354249.563807785, 4049.7590645502, 1235  
 1342, 359368.74595383, 15289.871148, 1235  
 1343, 359368.898026474, 13199.871148, 1235  
 1344, 359369.154526976, 9674.67398479631, 1235  
 1345, 359369.411017264, 6149.61721957922, 1235  
 1346, 359369.563807242, 4049.75857175495, 1235  
 1347, 364488.745954139, 15289.871148, 1235  
 1348, 364488.898026617, 13199.871148, 1235  
 1349, 364489.154525973, 9674.68592712056, 1235  
 1350, 364489.41101712, 6149.61352003502, 1235  
 1351, 364489.563806699, 4049.75807895971, 1235  
 1352, 369608.745954447, 15289.871148, 1235  
 1353, 369608.898026761, 13199.871148, 1235  
 1354, 369609.154524969, 9674.6978694448, 1235  
 1355, 369609.411016976, 6149.60982049082, 1235  
 1356, 369609.563806157, 4049.75758616447, 1235  
 1357, 374728.745954756, 15289.871148, 1235  
 1358, 374728.898026905, 13199.871148, 1235  
 1359, 374729.154523966, 9674.70981176904, 1235  
 1360, 374729.411016833, 6149.60612094663, 1235  
 1361, 374729.563805614, 4049.75709336923, 1235  
 1362, 379853.745955065, 15289.871148, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1363, 379853.898027048, 13199.871148, 1235  
 1364, 379854.154522961, 9674.72176575571, 1235  
 1365, 379854.411016689, 6149.60241778959, 1235  
 1366, 379854.563805071, 4049.75660009274, 1235  
 1367, 384978.999893869, 15289.871148, 1235  
 1368, 384978.999893869, 13199.871148, 1235  
 1369, 384978.999893869, 9674.73371938172, 1235  
 1370, 384978.999893869, 6149.59871492962, 1235  
 1371, 384978.999893869, 4049.75610687053, 1235  
 1372, 333769.063206057, 4049.76103577935, 1235  
 1373, 333769.053823314, 6149.6357175583, 1235  
 1374, 333769.038072865, 9674.61427290346, 1235  
 1375, 333769.022321172, 13199.871148, 1235  
 1376, 333769.012982552, 15289.871148, 1235  
 1377, 183649.996827596, 15289.871148, 1235  
 1378, 183649.996827596, 13199.871148, 1235  
 1379, 183649.996827596, 9674.26412246088, 1235  
 1380, 88478.3119709999, 9917.55931399998, 1235  
 1381, 93478.4267965, 10000.797195, 1235  
 1382, 98478.5405735, 10084.035347, 1235  
 1383, 103478.6564615, 10167.273631, 1235  
 1384, 108478.771301, 10250.5120035, 1235  
 1385, 113478.886145, 10333.750492, 1235  
 1386, 118479.0009945, 10416.98911, 1235  
 1387, 123479.1158505, 10500.2278705, 1235  
 1388, 128479.2307085, 10583.4662725, 1235  
 1389, 133501.99989, 10666.147153, 1235  
 1390, 385478.999893869, 10666.7348856243, 1235  
 1391, 138501.654410394, 10666.1588146202, 1235  
 1392, 143501.654412584, 10666.1704770462, 1235  
 1393, 148501.654414773, 10666.1821394722, 1235  
 1394, 153501.654416962, 10666.1938018983, 1235  
 1395, 158501.654419151, 10666.2054643243, 1235  
 1396, 163501.65442084, 10666.2171267503, 1235  
 1397, 168501.654423029, 10666.2287891764, 1235  
 1398, 173501.899255404, 10666.2404521734, 1235  
 1399, 178501.654427407, 10666.2521140284, 1235  
 1400, 188611.654433541, 10666.2756954538, 1235  
 1401, 193574.654436022, 10666.2872715779, 1235  
 1402, 198537.654438487, 10666.298847702, 1235  
 1403, 203490.455171048, 10666.3104000364, 1235  
 1404, 208489.983640392, 10666.3220613626, 1235  
 1405, 213489.876459049, 10666.3337235386, 1235  
 1406, 218489.654447777, 10666.3453854468, 1235  
 1407, 223489.654449992, 10666.3570478728, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1408, 228489.654452206, 10666.3687102989, 1235  
 1409, 233489.65445442, 10666.3803727249, 1235  
 1410, 238489.654456634, 10666.3920351509, 1235  
 1411, 243489.654458751, 10666.4036975769, 1235  
 1412, 248489.65446094, 10666.415360003, 1235  
 1413, 253649.304703, 10666.4273948108, 1235  
 1414, 258612.118602055, 10666.4389705008, 1235  
 1415, 263575.048691577, 10666.4505464618, 1235  
 1416, 268538.048693459, 10666.4621225859, 1235  
 1417, 273502.304703, 10666.4737016396, 1235  
 1418, 278502.154542577, 10666.4853637153, 1235  
 1419, 283502.154541597, 10666.4970261414, 1235  
 1420, 288502.154540617, 10666.5086885674, 1235  
 1421, 293502.154539637, 10666.5203509934, 1235  
 1422, 298501.849055773, 10666.5320127069, 1235  
 1423, 303502.030453369, 10666.543675556, 1235  
 1424, 308502.030453369, 10666.555337982, 1235  
 1425, 313502.154535467, 10666.5670006975, 1235  
 1426, 318502.154534736, 10666.5786631235, 1235  
 1427, 323502.154533756, 10666.5903255495, 1235  
 1428, 328648.999893869, 10666.6023304902, 1235  
 1429, 338889.09434804, 10666.626215359, 1235  
 1430, 344009.154529987, 10666.6381578236, 1235  
 1431, 349129.154528983, 10666.6501001478, 1235  
 1432, 354249.15452798, 10666.6620424721, 1235  
 1433, 359369.154526976, 10666.6739847963, 1235  
 1434, 364489.154525973, 10666.6859271206, 1235  
 1435, 369609.154524969, 10666.6978694448, 1235  
 1436, 374729.154523966, 10666.709811769, 1235  
 1437, 379854.154522961, 10666.7217657557, 1235  
 1438, 384978.999893869, 10666.7337193817, 1235  
 1439, 333769.038072865, 10666.6142729035, 1235  
 1440, 183649.996827596, 10666.2641224609, 1235  
 1441, 88478.3119709999, 7933.55931399998, 1235  
 1442, 93478.4267965, 8016.79719499999, 1235  
 1443, 98478.5405735, 8100.035347, 1235  
 1444, 103478.6564615, 8183.27363099999, 1235  
 1445, 108478.771301, 8266.51200349999, 1235  
 1446, 113478.886145, 8349.75049199998, 1235  
 1447, 118479.0009945, 8432.98910999997, 1235  
 1448, 123479.1158505, 8516.22787049999, 1235  
 1449, 128479.2307085, 8599.46627249998, 1235  
 1450, 133501.99989, 8682.147153, 1235  
 1451, 385478.999893869, 8682.73488562432, 1235  
 1452, 138501.654410394, 8682.15881462019, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1453, 143501.654412584, 8682.17047704622, 1235  
 1454, 148501.654414773, 8682.18213947225, 1235  
 1455, 153501.654416962, 8682.19380189827, 1235  
 1456, 158501.654419151, 8682.2054643243, 1235  
 1457, 163501.65442084, 8682.21712675033, 1235  
 1458, 168501.654423029, 8682.22878917635, 1235  
 1459, 173501.899255404, 8682.24045217344, 1235  
 1460, 178501.654427407, 8682.2521140284, 1235  
 1461, 188611.654433541, 8682.27569545383, 1235  
 1462, 193574.654436022, 8682.2872715779, 1235  
 1463, 198537.654438487, 8682.29884770198, 1235  
 1464, 203490.455171048, 8682.31040003641, 1235  
 1465, 208489.983640392, 8682.32206136259, 1235  
 1466, 213489.876459049, 8682.33372353862, 1235  
 1467, 218489.654447777, 8682.3453854468, 1235  
 1468, 223489.654449992, 8682.35704787283, 1235  
 1469, 228489.654452206, 8682.36871029885, 1235  
 1470, 233489.65445442, 8682.38037272488, 1235  
 1471, 238489.654456634, 8682.3920351509, 1235  
 1472, 243489.654458751, 8682.40369757693, 1235  
 1473, 248489.65446094, 8682.41536000296, 1235  
 1474, 253649.304703, 8682.42739481081, 1235  
 1475, 258612.118602055, 8682.4389705008, 1235  
 1476, 263575.048691577, 8682.4505464618, 1235  
 1477, 268538.048693459, 8682.46212258587, 1235  
 1478, 273502.304703, 8682.47370163957, 1235  
 1479, 278502.154542577, 8682.48536371534, 1235  
 1480, 283502.154541597, 8682.49702614136, 1235  
 1481, 288502.154540617, 8682.50868856738, 1235  
 1482, 293502.154539637, 8682.5203509934, 1235  
 1483, 298501.849055773, 8682.53201270688, 1235  
 1484, 303502.030453369, 8682.54367555601, 1235  
 1485, 308502.030453369, 8682.55533798203, 1235  
 1486, 313502.154535467, 8682.56700069747, 1235  
 1487, 318502.154534736, 8682.57866312349, 1235  
 1488, 323502.154533756, 8682.59032554951, 1235  
 1489, 328648.999893869, 8682.60233049016, 1235  
 1490, 338889.09434804, 8682.62621535896, 1235  
 1491, 344009.154529987, 8682.63815782358, 1235  
 1492, 349129.154528983, 8682.65010014782, 1235  
 1493, 354249.15452798, 8682.66204247207, 1235  
 1494, 359369.154526976, 8682.67398479631, 1235  
 1495, 364489.154525973, 8682.68592712056, 1235  
 1496, 369609.154524969, 8682.6978694448, 1235  
 1497, 374729.154523966, 8682.70981176904, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1498, 379854.154522961, 8682.72176575572, 1235  
 1499, 384978.999893869, 8682.73371938171, 1235  
 1500, 333769.038072865, 8682.61427290346, 1235  
 1501, 183649.996827596, 8682.26412246088, 1235  
 1502, 49.9998589999741, 7874.93557350001, 1235  
 1503, 499.999885999947, 7874.93557827678, 1235  
 1504, 5055.14788599999, 7874.93562662986, 1235  
 1505, 9611.08648349997, 7874.93567499134, 1235  
 1506, 14166.073869793, 7874.93572334652, 1235  
 1507, 18721.5738695831, 7874.93577170511, 1235  
 1508, 23277.0738696362, 7874.9358200637, 1235  
 1509, 27808.7618171198, 7941.73358230833, 1235  
 1510, 32362.9586365401, 8008.95973915614, 1235  
 1511, 36917.1502639506, 8076.18581095815, 1235  
 1512, 41501.9998899062, 8143.84399229933, 1235  
 1513, 46477.9917976656, 8226.47196903791, 1235  
 1514, 51478.1066981567, 8309.67554378849, 1235  
 1515, 56478.2216066976, 8392.87911858921, 1235  
 1516, 60478.5681697975, 8459.41769817944, 1235  
 1517, 64478.959612913, 8525.9861206612, 1235  
 1518, 68479.351054626, 8592.55454311847, 1235  
 1519, 73479.4656054719, 8675.75814147768, 1235  
 1520, 78479.5805456159, 8758.96171645475, 1235  
 1521, 83501.99989, 8842.57778937105, 1235  
 1522, 88478.3119709999, 8925.55931399998, 1235  
 1523, 499.999885999947, 9185.11549323488, 0  
 1524, 5055.14788599999, 9197.71155234924, 0  
 1525, 9611.08648349997, 9210.30979765225, 0  
 1526, 14165.7050250073, 9222.90439268894, 0  
 1527, 18721.0282548149, 9235.50093635507, 0  
 1528, 23276.3482754356, 9248.09747114703, 0  
 1529, 27816.0221227021, 9260.6507405776, 0  
 1530, 36924.7954992254, 9322.09026446251, 0  
 1531, 41501.99989, 9371.17975861616, 0  
 1532, 46486.1004117453, 9424.63312283922, 0  
 1533, 51486.1657036009, 9478.25770565381, 0  
 1534, 56486.2305720979, 9531.88228392798, 0  
 1535, 60486.3919372665, 9574.78312059258, 0  
 1536, 499.999885999947, 9567.44289189982, 0  
 1537, 5055.14788599999, 9582.0485364743, 0  
 1538, 9611.08648349997, 9596.65671602373, 0  
 1539, 14166.419648684, 9611.26295431259, 0  
 1540, 18722.0747706987, 9625.8702249251, 0  
 1541, 23277.7261714313, 9640.47748360568, 0  
 1542, 32355.6459598326, 9751.24039991187, 0

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1543, 36909.6106728427, 6847.49764096015, 0  
 1544, 41501.999889814, 6944.56706149884, 0  
 1545, 46470.0267742334, 7049.57634274814, 0  
 1546, 51470.1451770165, 7155.26394304764, 0  
 1547, 56470.2622410457, 7260.95151504987, 0  
 1548, 118478.409176356, 9363.87755388048, 0  
 1549, 123477.89534401, 9386.00445260833, 0  
 1550, 128477.34047983, 9408.13116973608, 0  
 1551, 133501.991412164, 9430.36944354947, 0  
 1552, 138501.61838497, 9452.49696545764, 0  
 1553, 143501.621981828, 9474.62615424155, 0  
 1554, 148501.625578678, 9496.75534302543, 0  
 1555, 153501.629175521, 9518.88453180928, 0  
 1556, 158501.632772355, 9541.01372059309, 0  
 1557, 163501.63636865, 9563.14290937451, 0  
 1558, 168501.639965476, 9585.27209815828, 0  
 1559, 173501.899255404, 9607.40241859742, 0  
 1560, 178501.647159105, 9629.53047572573, 0  
 1561, 183649.996827596, 9652.31621968224, 0  
 1562, 29737.7065353542, 13199.871148, 0  
 1563, 29678.470256742, 2693.28124439666, 0  
 1564, 38948.5907004669, 13199.871148, 0  
 1565, 38884.4840593134, 2999.77826967928, 0  
 1566, 42646.5659298424, 3125.02975498823, 0  
 1567, 42711.4585000734, 13199.871148, 0  
 1568, 81312.3220248928, 13199.871148, 0  
 1569, 81245.2798365281, 4410.10180249407, 0  
 1570, 84813.5376376306, 13199.871148, 0  
 1571, 84745.1227687074, 4526.62253257446, 0  
 1572, 97314.1278323477, 13199.871148, 0  
 1573, 97243.6058356989, 4942.73616935, 0  
 1574, 122315.557806782, 13199.871148, 0  
 1575, 122240.324456338, 5774.95520202667, 0  
 1576, 131116.434224263, 13199.871148, 0  
 1577, 131040.597410471, 6067.13370726809, 0  
 1578, 136602.22742412, 13199.871148, 0  
 1579, 145402.227423493, 13199.871148, 0  
 1580, 190412.227421569, 13199.871148, 0  
 1581, 201538.227423024, 13199.871148, 0  
 1582, 175101.899255403, 6149.75036524402, 0  
 1583, 181101.081613853, 6149.74603043146, 0  
 1584, 206389.983640392, 13199.871148, 0  
 1585, 211689.876459049, 13199.871148, 0  
 1586, 220290.227423478, 13199.871148, 0  
 1587, 261712.118602055, 13199.871148, 0

## PROJECT TITLE :

|  | Company |     | Client    |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1588, 271438.621646604, 13199.871148, 0  
1589, 241189.081619393, 6149.70261281199, 0  
1590, 250089.081620097, 6149.69618196368, 0  
1591, 276601.898025505, 13199.871148, 0  
1592, 316601.89802572, 13199.871148, 0  
1593, 325501.898025734, 13199.871148, 0  
1594, 266837.475842662, 6149.68408012292, 0  
1595, 326502.411017502, 6149.64096819623, 0  
1596, 331969.022321172, 13199.871148, 0  
1597, 342108.898026043, 13199.871148, 0  
1598, 331969.053823314, 6149.6370181793, 0  
1599, 342109.411017695, 6149.62969108953, 0  
1600, 249.999887999962, 15739.871148, 1235  
1601, 249.999889572384, 15289.871148, 1235  
1602, 249.999896875524, 13199.871148, 1235  
1603, 274.999877541617, 9183.87113700001, 1235  
1604, 274.99987249996, 7874.9355758884, 1235  
1605, 274.999867458304, 6566.00001477679, 1235  
1606, 249.999934089486, 2550.00001024118, 1235  
1607, 249.999941427552, 450.000010826884, 1235  
1608, 249.999942999973, 1.08269305187925e-005, 1235  
1609, 2777.57388599997, 15739.871148, 1235  
1610, 2777.57388599997, 15289.871148, 1235  
1611, 2777.57388599997, 13199.871148, 1235  
1612, 2777.57388599997, 9183.87113700001, 1235  
1613, 2777.57388599997, 7874.93560245332, 1235  
1614, 2777.57388599997, 6566.00006790664, 1235  
1615, 2777.57388599997, 2550.0001198735, 1235  
1616, 2777.57388599997, 450.000120290352, 1235  
1617, 2777.57388599997, 0.000120290394978184, 1235  
1618, 7333.11718474998, 15739.871148, 1235  
1619, 7333.11718474998, 15289.871148, 1235  
1620, 7333.11718474998, 13199.871148, 1235  
1621, 7333.11718474998, 9183.87113700001, 1235  
1622, 7333.11718474998, 7874.9356508106, 1235  
1623, 7333.11718474998, 6566.0001646212, 1235  
1624, 7333.11718474998, 2550.00031746803, 1235  
1625, 7333.11718474998, 450.000317580551, 1235  
1626, 7333.11718474998, 0.000317580583220067, 1235  
1627, 11887.5041351602, 15739.871148, 1235  
1628, 11887.56570193, 15289.871148, 1235  
1629, 11887.851645372, 13199.871148, 1235  
1630, 11888.4010945902, 9183.87113700001, 1235  
1631, 11888.5801766465, 7874.93569916893, 1235  
1632, 11888.7592587027, 6566.00026133785, 1235

## PROJECT TITLE :

|  | Company |     | Client    |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1633, 11889.3087078779, 2550.00051496774, 1235  
1634, 11889.5960194703, 450.000514911266, 1235  
1635, 11889.6575862401, 0.000514913954252627, 1235  
1636, 16441.1708273333, 15739.871148, 1235  
1637, 16441.3226237562, 15289.871148, 1235  
1638, 16442.0276338094, 13199.871148, 1235  
1639, 16443.3823325563, 9183.87113700001, 1235  
1640, 16443.8238696881, 7874.93574752582, 1235  
1641, 16444.2654068198, 6566.00035805162, 1235  
1642, 16445.6201054403, 2550.00071233214, 1235  
1643, 16446.3284887473, 450.000712252966, 1235  
1644, 16446.4802851703, 0.00071225955616816, 1235  
1645, 20995.6689081974, 15739.871148, 1235  
1646, 20995.8780304041, 15289.871148, 1235  
1647, 20996.8492868751, 13199.871148, 1235  
1648, 20998.7155863958, 9183.87113700001, 1235  
1649, 20999.3238696097, 7874.9357958844, 1235  
1650, 20999.9321528236, 6566.0004547688, 1235  
1651, 21001.7984521246, 2550.00090962692, 1235  
1652, 21002.7743557558, 450.000909582253, 1235  
1653, 21002.9834779625, 0.000909591319209202, 1235  
1654, 25562.3032709418, 15739.871148, 1235  
1655, 25561.1835953672, 15289.871148, 1235  
1656, 25555.9833243648, 13199.871148, 1235  
1657, 25546.1136333136, 9206.1775995506, 1235  
1658, 25542.917843378, 7908.33470118601, 1235  
1659, 25539.7220534425, 6610.49180282142, 1235  
1660, 25529.7050093698, 2590.03016609031, 1235  
1661, 25524.475594182, 489.255824295068, 1235  
1662, 25523.3550052134, 39.0898939488106, 1235  
1663, 30129.7982855667, 15739.871148, 1235  
1664, 30127.2515144016, 15289.871148, 1235  
1665, 30115.4231772124, 13199.871148, 1235  
1666, 30093.0772694789, 9250.86424096437, 1235  
1667, 30085.86022683, 7975.34666073223, 1235  
1668, 30078.643184181, 6699.8290805001, 1235  
1669, 30056.0440932135, 2705.85185969218, 1235  
1670, 30044.1503335305, 604.292347015592, 1235  
1671, 30041.6016707417, 153.958165790034, 1235  
1672, 34686.0424317503, 15739.871148, 1235  
1673, 34683.3535626985, 15289.871148, 1235  
1674, 34670.8652597687, 13199.871148, 1235  
1675, 34647.5399574794, 9295.62458154687, 1235  
1676, 34640.0544502453, 8042.57277505714, 1235  
1677, 34632.5689430113, 6789.52096856741, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1678, 34609.0786822964, 2857.43663764903, 1235  
 1679, 34596.5211744604, 755.855026968601, 1235  
 1680, 34593.8302799242, 305.516110402808, 1235  
 1681, 39233.0883878511, 15739.871148, 1235  
 1682, 39231.7077218362, 15289.871148, 1235  
 1683, 39225.2952952334, 13199.871148, 1235  
 1684, 39213.3851596343, 9340.49678718243, 1235  
 1685, 39209.5750769284, 8110.01490162874, 1235  
 1686, 39205.7649942225, 6879.53301607504, 1235  
 1687, 39193.7957306031, 3010.07622372972, 1235  
 1688, 39187.3477353764, 908.698018254476, 1235  
 1689, 39185.9660221135, 458.402688433001, 1235  
 1690, 44015.2597226384, 15739.871148, 1235  
 1691, 44013.7484086932, 15289.871148, 1235  
 1692, 44006.7291950367, 13199.871148, 1235  
 1693, 43994.0283183579, 9390.5606160242, 1235  
 1694, 43989.9958437859, 8185.15798066862, 1235  
 1695, 43985.9633692139, 6979.75534531303, 1235  
 1696, 43973.2307735117, 3169.1985817309, 1235  
 1697, 43966.1578493624, 1067.79957053391, 1235  
 1698, 43964.6422227587, 617.499782318417, 1235  
 1699, 49028.7709834655, 15739.871148, 1235  
 1700, 49025.7196895454, 15289.871148, 1235  
 1701, 49011.5481244497, 13199.871148, 1235  
 1702, 48986.0952137334, 9445.85569131787, 1235  
 1703, 48978.0492479111, 8268.0737564132, 1235  
 1704, 48970.0032820888, 7090.29182150853, 1235  
 1705, 48944.4870065976, 3334.70726794078, 1235  
 1706, 48930.2070134162, 1233.06831070692, 1235  
 1707, 48927.1470148768, 782.717105513926, 1235  
 1708, 54029.2861241794, 15739.871148, 1235  
 1709, 54026.1760971651, 15289.871148, 1235  
 1710, 54011.7317494764, 13199.871148, 1235  
 1711, 53986.1721593429, 9501.30227218245, 1235  
 1712, 53978.1641524272, 8351.27733118885, 1235  
 1713, 53970.1561455115, 7201.25239019525, 1235  
 1714, 53944.5333354543, 3501.174466623, 1235  
 1715, 53929.9784972772, 1399.52635876054, 1235  
 1716, 53926.8596033818, 949.173192756738, 1235  
 1717, 58529.593493221, 15739.871148, 1235  
 1718, 58526.4451762912, 15289.871148, 1235  
 1719, 58511.8229932168, 13199.871148, 1235  
 1720, 58486.2961749707, 9551.17547915495, 1235  
 1721, 58478.3948882476, 8426.14840838432, 1235  
 1722, 58470.4936015244, 7301.1213376137, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1723, 58444.9304438241, 3651.00677813893, 1235  
 1724, 58430.2116129631, 1549.35321037594, 1235  
 1725, 58427.0575777785, 1098.99887440858, 1235  
 1726, 62529.6825825457, 15739.871148, 1235  
 1727, 62526.5208537366, 15289.871148, 1235  
 1728, 62511.8363799343, 13199.871148, 1235  
 1729, 62486.5121294738, 9595.50515500778, 1235  
 1730, 62478.7638913553, 8492.70190942032, 1235  
 1731, 62471.0156532368, 7389.89866383286, 1235  
 1732, 62445.6820700513, 3784.20432696233, 1235  
 1733, 62430.9157063806, 1682.54917670974, 1235  
 1734, 62427.7514855939, 1232.19450163178, 1235  
 1735, 66529.7753350171, 15739.871148, 1235  
 1736, 66526.6030126604, 15289.871148, 1235  
 1737, 66511.8693377149, 13199.871148, 1235  
 1738, 66486.7729638098, 9639.86467375471, 1235  
 1739, 66479.1553337695, 8559.27033188984, 1235  
 1740, 66471.5377037292, 7478.67599002497, 1235  
 1741, 66446.4323933737, 3917.40183241546, 1235  
 1742, 66431.6165425085, 1815.74503460257, 1235  
 1743, 66428.4417173229, 1365.39000647094, 1235  
 1744, 71030.1209184958, 15739.871148, 1235  
 1745, 71026.9091259234, 15289.871148, 1235  
 1746, 71011.9921337538, 13199.871148, 1235  
 1747, 70986.9415123842, 9689.76774741966, 1235  
 1748, 70979.408330049, 8634.15634229808, 1235  
 1749, 70971.8751477137, 7578.5449371765, 1235  
 1750, 70946.8159077034, 4067.23369131446, 1235  
 1751, 70931.8156729991, 1965.5707547543, 1235  
 1752, 70928.6013369908, 1515.21441118367, 1235  
 1753, 76030.7337756203, 15739.871148, 1235  
 1754, 76027.4520167978, 15289.871148, 1235  
 1755, 76012.2100702662, 13199.871148, 1235  
 1756, 75987.0181699654, 9745.21435273526, 1235  
 1757, 75979.5230755439, 8717.35992896622, 1235  
 1758, 75972.0279811224, 7689.50550519717, 1235  
 1759, 75946.8274746077, 4233.6997325773, 1235  
 1760, 75931.5002522268, 2132.02590949155, 1235  
 1761, 75928.2158474308, 1681.66723311158, 1235  
 1762, 81016.5241294646, 15739.871148, 1235  
 1763, 81014.8652997763, 15289.871148, 1235  
 1764, 81007.1609574464, 13199.871148, 1235  
 1765, 80994.5282929207, 9800.7434165575, 1235  
 1766, 80990.7902178079, 8800.7697529129, 1235  
 1767, 80987.0521426952, 7800.7960892683, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1768, 80974.2903415387, 4401.07971366496, 1235  
 1769, 80966.6455650699, 2299.66166308609, 1235  
 1770, 80965.0073986837, 1849.3577951375, 1235  
 1771, 86018.2351496005, 15739.871148, 1235  
 1772, 86016.3808686543, 15289.871148, 1235  
 1773, 86007.7687638153, 13199.871148, 1235  
 1774, 85990.1559305, 9873.05425167946, 1235  
 1775, 85990.1559305, 7895.08285169158, 1235  
 1776, 85972.4121006764, 4567.48283732895, 1235  
 1777, 85963.8543789051, 2466.03439195822, 1235  
 1778, 85962.0205813827, 2015.72401083582, 1235  
 1779, 85990.1559305, 8884.06855168552, 1235  
 1780, 91034.8735455845, 15739.871148, 1235  
 1781, 91031.1189402147, 15289.871148, 1235  
 1782, 91013.6808841636, 13199.871148, 1235  
 1783, 96035.7046002227, 15739.871148, 1235  
 1784, 96031.8550417915, 15289.871148, 1235  
 1785, 96013.9759815221, 13199.871148, 1235  
 1786, 101036.58757775, 15739.871148, 1235  
 1787, 101032.637171628, 15289.871148, 1235  
 1788, 101014.289729862, 13199.871148, 1235  
 1789, 106037.527502372, 15739.871148, 1235  
 1790, 106033.469780124, 15289.871148, 1235  
 1791, 106014.623914574, 13199.871148, 1235  
 1792, 111038.530067779, 15739.871148, 1235  
 1793, 111034.357839329, 15289.871148, 1235  
 1794, 111014.980156085, 13199.871148, 1235  
 1795, 116039.601754835, 15739.871148, 1235  
 1796, 116035.307125579, 15289.871148, 1235  
 1797, 116015.360958589, 13199.871148, 1235  
 1798, 90978.3693837499, 9959.17825449999, 1235  
 1799, 95978.483685, 10042.416271, 1235  
 1800, 100978.5985175, 10125.654489, 1235  
 1801, 105978.71388125, 10208.89281725, 1235  
 1802, 110978.828723, 10292.13124775, 1235  
 1803, 115978.94356975, 10375.369801, 1235  
 1804, 90978.3693837499, 8967.17825449999, 1235  
 1805, 90978.3693837499, 7975.17825449999, 1235  
 1806, 95978.483685, 9050.416271, 1235  
 1807, 95978.483685, 8058.41627099999, 1235  
 1808, 100978.5985175, 9133.65448899999, 1235  
 1809, 100978.5985175, 8141.65448899999, 1235  
 1810, 105978.71388125, 9216.89281724999, 1235  
 1811, 105978.71388125, 8224.89281724999, 1235  
 1812, 110978.828723, 9300.13124774998, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1813, 110978.828723, 8308.13124774998, 1235  
 1814, 115978.94356975, 9383.36980099997, 1235  
 1815, 115978.94356975, 8391.36980099997, 1235  
 1816, 90943.0452454856, 4732.97077891835, 1235  
 1817, 95942.9789739622, 4899.43422862537, 1235  
 1818, 100942.894429271, 5065.89706976881, 1235  
 1819, 105942.789823278, 5232.35924301129, 1235  
 1820, 110942.662725898, 5398.82066773251, 1235  
 1821, 115942.511032169, 5565.28127355214, 1235  
 1822, 90925.509173681, 2631.22341634135, 1235  
 1823, 90921.7514440085, 2180.84898149323, 1235  
 1824, 95924.9996256084, 2797.67210774098, 1235  
 1825, 95921.1469081044, 2347.29451045051, 1235  
 1826, 100924.44392582, 2964.11926261089, 1235  
 1827, 100920.490246509, 2513.73830398575, 1235  
 1828, 105923.837603752, 3130.56473260121, 1235  
 1829, 105919.776413853, 2680.18019461194, 1235  
 1830, 110923.175521977, 3297.00834572003, 1235  
 1831, 110918.999692565, 2846.6199910379, 1235  
 1832, 115922.451949716, 3463.44991159664, 1235  
 1833, 115918.153574906, 3013.05747699499, 1235  
 1834, 121040.749969046, 15739.871148, 1235  
 1835, 121036.32419858, 15289.871148, 1235  
 1836, 121015.768953528, 13199.871148, 1235  
 1837, 126041.98321347, 15739.871148, 1235  
 1838, 126037.416590225, 15289.871148, 1235  
 1839, 126016.207162269, 13199.871148, 1235  
 1840, 131022.31106034, 15739.871148, 1235  
 1841, 131019.991256622, 15289.871148, 1235  
 1842, 131009.217057131, 13199.871148, 1235  
 1843, 136002.320062848, 15739.871148, 1235  
 1844, 136002.283494893, 15289.871148, 1235  
 1845, 136002.11365706, 13199.871148, 1235  
 1846, 141002.64023532, 15739.871148, 1235  
 1847, 141002.56709945, 15289.871148, 1235  
 1848, 141002.227423963, 13199.871148, 1235  
 1849, 146002.640234569, 15739.871148, 1235  
 1850, 146002.567098776, 15289.871148, 1235  
 1851, 146002.22742365, 13199.871148, 1235  
 1852, 151002.640233818, 15739.871148, 1235  
 1853, 151002.567098103, 15289.871148, 1235  
 1854, 151002.227423336, 13199.871148, 1235  
 1855, 156002.640233068, 15739.871148, 1235  
 1856, 156002.56709743, 15289.871148, 1235  
 1857, 156002.227423023, 13199.871148, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1858, 161002.640232956, 15739.871148, 1235  
 1859, 161002.56709733, 15289.871148, 1235  
 1860, 161002.227422977, 13199.871148, 1235  
 1861, 120979.0584225, 10458.60849025, 1235  
 1862, 125979.1732795, 10541.8470715, 1235  
 1863, 130990.61529925, 10624.80671275, 1235  
 1864, 136001.827150197, 10666.1529838101, 1235  
 1865, 141001.654411489, 10666.1646458332, 1235  
 1866, 146001.654413678, 10666.1763082592, 1235  
 1867, 151001.654415867, 10666.1879706853, 1235  
 1868, 156001.654418056, 10666.1996331113, 1235  
 1869, 161001.654419995, 10666.2112955373, 1235  
 1870, 120979.0584225, 9466.60849024998, 1235  
 1871, 120979.0584225, 8474.60849024998, 1235  
 1872, 125979.1732795, 9549.84707149999, 1235  
 1873, 125979.1732795, 8557.84707149999, 1235  
 1874, 130990.61529925, 9632.80671274999, 1235  
 1875, 130990.61529925, 8640.80671274999, 1235  
 1876, 136001.827150197, 9674.1529838101, 1235  
 1877, 136001.827150197, 8682.1529838101, 1235  
 1878, 141001.654411489, 9674.16464583321, 1235  
 1879, 141001.654411489, 8682.16464583321, 1235  
 1880, 146001.654413678, 9674.17630825923, 1235  
 1881, 146001.654413678, 8682.17630825924, 1235  
 1882, 151001.654415867, 9674.18797068526, 1235  
 1883, 151001.654415867, 8682.18797068526, 1235  
 1884, 156001.654418056, 9674.19963311129, 1235  
 1885, 156001.654418056, 8682.19963311129, 1235  
 1886, 161001.654419995, 9674.21129553731, 1235  
 1887, 161001.654419995, 8682.21129553731, 1235  
 1888, 120942.332106371, 5731.74097244692, 1235  
 1889, 125942.122921782, 5898.1996641767, 1235  
 1890, 130971.943816086, 6064.86941763154, 1235  
 1891, 136001.479442578, 6149.04345111637, 1235  
 1892, 141001.081613037, 6149.77500537722, 1235  
 1893, 146001.08161335, 6149.77139254109, 1235  
 1894, 151001.081613663, 6149.76777970496, 1235  
 1895, 156001.081613977, 6149.76416686883, 1235  
 1896, 161001.081613523, 6149.7605540327, 1235  
 1897, 120921.660297203, 3629.88921131641, 1235  
 1898, 120917.23062381, 3179.49240535779, 1235  
 1899, 125920.792997471, 3796.32599254735, 1235  
 1900, 125916.222299403, 3345.9244914352, 1235  
 1901, 133471.545986389, 6065.60277831045, 1235  
 1902, 133460.539868022, 3964.66177500496, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1903, 133458.181414034, 3514.4598080213, 1235  
 1904, 141000.740313054, 4049.7795895513, 1235  
 1905, 141000.667177184, 3599.77958955842, 1235  
 1906, 146000.740314238, 4049.77910830595, 1235  
 1907, 146000.667178445, 3599.77910831307, 1235  
 1908, 151000.740315422, 4049.7786270606, 1235  
 1909, 151000.667179706, 3599.77862706771, 1235  
 1910, 156000.740316605, 4049.77814581524, 1235  
 1911, 156000.667180968, 3599.77814582235, 1235  
 1912, 161000.740316715, 4049.77766456989, 1235  
 1913, 161000.667181088, 3599.777664577, 1235  
 1914, 166002.640232845, 15739.871148, 1235  
 1915, 166002.56709723, 15289.871148, 1235  
 1916, 166002.22742293, 13199.871148, 1235  
 1917, 166001.654421934, 10666.2229579633, 1235  
 1918, 166001.654421934, 9674.22295796334, 1235  
 1919, 166001.654421934, 8682.22295796334, 1235  
 1920, 166001.08161307, 6149.75694119658, 1235  
 1921, 166000.740316824, 4049.77718332453, 1235  
 1922, 166000.667181209, 3599.77718333164, 1235  
 1923, 171002.269743937, 15739.871148, 1235  
 1924, 171002.233176149, 15289.871148, 1235  
 1925, 171002.063339089, 13199.871148, 1235  
 1926, 171001.776839216, 10666.2346206749, 1235  
 1927, 171001.776839216, 9674.2346206749, 1235  
 1928, 171001.776839216, 8682.2346206749, 1235  
 1929, 171001.490434315, 6149.75332806505, 1235  
 1930, 171001.31978641, 4049.77670202341, 1235  
 1931, 171001.283218622, 3599.776702027, 1235  
 1932, 176002.269743186, 15739.871148, 1235  
 1933, 176002.233175475, 15289.871148, 1235  
 1934, 176002.063338775, 13199.871148, 1235  
 1935, 176001.776841406, 10666.2462831009, 1235  
 1936, 176001.776841406, 9674.24628310092, 1235  
 1937, 176001.776841406, 8682.24628310092, 1235  
 1938, 176001.490434629, 6149.74971522892, 1235  
 1939, 176001.319787594, 4049.77622077805, 1235  
 1940, 176001.283219883, 3599.77622078164, 1235  
 1941, 181076.318529282, 15739.871148, 1235  
 1942, 181076.281961572, 15289.871148, 1235  
 1943, 181076.112124871, 13199.871148, 1235  
 1944, 181075.825627502, 10666.2581182446, 1235  
 1945, 181075.825627502, 9674.25811824464, 1235  
 1946, 181075.825627502, 8682.25811824464, 1235  
 1947, 181075.539220725, 6149.74604888756, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

1948, 181075.36857369, 4049.77573240557, 1235  
 1949, 181075.332005979, 3599.77573240916, 1235  
 1950, 186131.318527956, 15739.871148, 1235  
 1951, 186131.28196043, 15289.871148, 1235  
 1952, 186131.112124583, 13199.871148, 1235  
 1953, 186130.825630569, 10666.2699089574, 1235  
 1954, 186130.825630569, 9674.26990895736, 1235  
 1955, 186130.825630569, 8682.26990895735, 1235  
 1956, 186130.539222721, 6149.74239631023, 1235  
 1957, 186130.368577058, 4049.77524586652, 1235  
 1958, 186130.332009531, 3599.77524587011, 1235  
 1959, 191094.14022885, 15739.871148, 1235  
 1960, 191094.067093779, 15289.871148, 1235  
 1961, 191093.727422005, 13199.871148, 1235  
 1962, 191093.154434782, 10666.2814835159, 1235  
 1963, 191093.154434782, 9674.28148351587, 1235  
 1964, 191093.154434782, 8682.28148351587, 1235  
 1965, 191092.581617718, 6149.73881090102, 1235  
 1966, 191092.240326564, 4049.77476829097, 1235  
 1967, 191092.167191493, 3599.77476829808, 1235  
 1968, 196057.140229675, 15739.871148, 1235  
 1969, 196057.067094587, 15289.871148, 1235  
 1970, 196056.727422732, 13199.871148, 1235  
 1971, 196056.154437254, 10666.2930596399, 1235  
 1972, 196056.154437254, 9674.29305963994, 1235  
 1973, 196056.154437254, 8682.29305963994, 1235  
 1974, 196055.581617591, 6149.73522479988, 1235  
 1975, 196055.240326861, 4049.77429060683, 1235  
 1976, 196055.167191773, 3599.77429061394, 1235  
 1977, 201014.547700508, 15739.871148, 1235  
 1978, 201014.511132963, 15289.871148, 1235  
 1979, 201014.341297036, 13199.871148, 1235  
 1980, 201014.054804767, 10666.3046238692, 1235  
 1981, 201014.054804767, 9674.3046238692, 1235  
 1982, 201014.054804767, 8682.3046238692, 1235  
 1983, 201013.76839432, 6149.73164217662, 1235  
 1984, 201013.597749081, 4049.77381336954, 1235  
 1985, 201013.561181537, 3599.77381337312, 1235  
 1986, 205990.21940572, 15739.871148, 1235  
 1987, 205990.21940572, 15289.871148, 1235  
 1988, 205990.21940572, 13199.871148, 1235  
 1989, 205990.21940572, 10666.3162306995, 1235  
 1990, 205990.21940572, 9674.3162306995, 1235  
 1991, 205990.21940572, 8682.3162306995, 1235  
 1992, 205990.21940572, 6149.72804635621, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

1993, 205990.21940572, 4049.77333437433, 1235  
 1994, 205990.21940572, 3599.77333437439, 1235  
 1995, 210989.93004972, 15739.871148, 1235  
 1996, 210989.93004972, 15289.871148, 1235  
 1997, 210989.93004972, 13199.871148, 1235  
 1998, 210989.93004972, 10666.3278924506, 1235  
 1999, 210989.93004972, 9674.3278924506, 1235  
 2000, 210989.93004972, 8682.3278924506, 1235  
 2001, 210989.93004972, 6149.72443372916, 1235  
 2002, 210989.93004972, 4049.77285315683, 1235  
 2003, 210989.93004972, 3599.77285315689, 1235  
 2004, 215990.258344276, 15739.871148, 1235  
 2005, 215990.221776813, 15289.871148, 1235  
 2006, 215990.051941263, 13199.871148, 1235  
 2007, 215989.765453413, 10666.3395544927, 1235  
 2008, 215989.765453413, 9674.33955449271, 1235  
 2009, 215989.765453413, 8682.33955449271, 1235  
 2010, 215989.479038649, 6149.72082121892, 1235  
 2011, 215989.308394805, 4049.77237197131, 1235  
 2012, 215989.271827342, 3599.77237197488, 1235  
 2013, 220990.640229185, 15739.871148, 1235  
 2014, 220990.567094295, 15289.871148, 1235  
 2015, 220990.227423359, 13199.871148, 1235  
 2016, 220989.654448884, 10666.3512166598, 1235  
 2017, 220989.654448884, 9674.35121665981, 1235  
 2018, 220989.654448884, 8682.35121665981, 1235  
 2019, 220989.081618391, 6149.71720866995, 1235  
 2020, 220988.740331123, 4049.77189078063, 1235  
 2021, 220988.667196233, 3599.77189078772, 1235  
 2022, 225990.640228549, 15739.871148, 1235  
 2023, 225990.56709373, 15289.871148, 1235  
 2024, 225990.227423123, 13199.871148, 1235  
 2025, 225989.654451099, 10666.3628790858, 1235  
 2026, 225989.654451099, 9674.36287908584, 1235  
 2027, 225989.654451099, 8682.36287908584, 1235  
 2028, 225989.081618678, 6149.71359583382, 1235  
 2029, 225988.740332249, 4049.77140953527, 1235  
 2030, 225988.66719743, 3599.77140954237, 1235  
 2031, 230990.640227913, 15739.871148, 1235  
 2032, 230990.567093165, 15289.871148, 1235  
 2033, 230990.227422887, 13199.871148, 1235  
 2034, 230989.654453313, 10666.3745415119, 1235  
 2035, 230989.654453313, 9674.37454151186, 1235  
 2036, 230989.654453313, 8682.37454151187, 1235  
 2037, 230989.081618964, 6149.70998299769, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

2038, 230988.740333375, 4049.77092828992, 1235  
 2039, 230988.667198626, 3599.77092829701, 1235  
 2040, 235990.640227277, 15739.871148, 1235  
 2041, 235990.5670926, 15289.871148, 1235  
 2042, 235990.227422651, 13199.871148, 1235  
 2043, 235989.654455527, 10666.3862039379, 1235  
 2044, 235989.654455527, 9674.38620393789, 1235  
 2045, 235989.654455527, 8682.38620393789, 1235  
 2046, 235989.081619251, 6149.70637016156, 1235  
 2047, 235988.740334501, 4049.77044704457, 1235  
 2048, 235988.667199823, 3599.77044705165, 1235  
 2049, 240990.64022642, 15739.871148, 1235  
 2050, 240990.567091826, 15289.871148, 1235  
 2051, 240990.227422266, 13199.871148, 1235  
 2052, 240989.654457693, 10666.3978663639, 1235  
 2053, 240989.654457693, 9674.39786636392, 1235  
 2054, 240989.654457693, 8682.39786636392, 1235  
 2055, 240989.081619589, 6149.70275732543, 1235  
 2056, 240988.740335739, 4049.76996579921, 1235  
 2057, 240988.667201145, 3599.7699658063, 1235  
 2058, 245990.640225505, 15739.871148, 1235  
 2059, 245990.567090998, 15289.871148, 1235  
 2060, 245990.227421842, 13199.871148, 1235  
 2061, 245989.654459846, 10666.4095287899, 1235  
 2062, 245989.654459846, 9674.40952878994, 1235  
 2063, 245989.654459846, 8682.40952878994, 1235  
 2064, 245989.081619941, 6149.6991444893, 1235  
 2065, 245988.740337006, 4049.76948455386, 1235  
 2066, 245988.667202498, 3599.76948456094, 1235  
 2067, 251069.972464065, 15739.871148, 1235  
 2068, 251069.935896831, 15289.871148, 1235  
 2069, 251069.766062343, 13199.871148, 1235  
 2070, 251069.47958197, 10666.4213774069, 1235  
 2071, 251069.47958197, 9674.42137740688, 1235  
 2072, 251069.47958197, 8682.42137740688, 1235  
 2073, 251069.193161549, 6149.6954737672, 1235  
 2074, 251069.022520299, 4049.76899558142, 1235  
 2075, 251068.985953065, 3599.76899558499, 1235  
 2076, 256130.711652527, 15739.871148, 1235  
 2077, 256130.711652527, 15289.871148, 1235  
 2078, 256130.711652527, 13199.871148, 1235  
 2079, 256130.711652527, 10666.4331826558, 1235  
 2080, 256130.711652527, 9674.4331826558, 1235  
 2081, 256130.711652527, 8682.4331826558, 1235  
 2082, 256130.711652527, 6149.69181647982, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

2083, 256130.711652527, 4049.76850839854, 1235  
 2084, 256130.711652527, 3599.76850839859, 1235  
 2085, 261094.076526052, 15739.871148, 1235  
 2086, 261094.039958817, 15289.871148, 1235  
 2087, 261093.870124329, 13199.871148, 1235  
 2088, 261093.583646816, 10666.4447584813, 1235  
 2089, 261093.583646816, 9674.4447584813, 1235  
 2090, 261093.583646816, 8682.4447584813, 1235  
 2091, 261093.29722265, 6149.68823067814, 1235  
 2092, 261093.126582167, 4049.76803077072, 1235  
 2093, 261093.090014933, 3599.76803077428, 1235  
 2094, 266057.534450049, 15739.871148, 1235  
 2095, 266057.46131558, 15289.871148, 1235  
 2096, 266057.121646604, 13199.871148, 1235  
 2097, 266056.548692518, 10666.4563345238, 1235  
 2098, 266056.548692518, 9674.45633452383, 1235  
 2099, 266056.548692518, 8682.45633452384, 1235  
 2100, 266055.975842953, 6149.68464480921, 1235  
 2101, 266055.634562241, 4049.76755313394, 1235  
 2102, 266055.561427773, 3599.76755314102, 1235  
 2103, 271020.669576524, 15739.871148, 1235  
 2104, 271020.63300929, 15289.871148, 1235  
 2105, 271020.463174802, 13199.871148, 1235  
 2106, 271020.176698229, 10666.4679121127, 1235  
 2107, 271020.176698229, 9674.46791211272, 1235  
 2108, 271020.176698229, 8682.46791211272, 1235  
 2109, 271019.890272831, 6149.68105804733, 1235  
 2110, 271019.719632601, 4049.76707534536, 1235  
 2111, 271019.683065367, 3599.76707534892, 1235  
 2112, 276002.008955449, 15739.871148, 1235  
 2113, 276002.025327088, 15289.871148, 1235  
 2114, 276002.101364252, 13199.871148, 1235  
 2115, 276002.229622788, 10666.4795326775, 1235  
 2116, 276002.229622788, 9674.47953267745, 1235  
 2117, 276002.229622788, 8682.47953267745, 1235  
 2118, 276002.357860366, 6149.67745787955, 1235  
 2119, 276002.434258045, 4049.76659576371, 1235  
 2120, 276002.450629684, 3599.76659576217, 1235  
 2121, 281001.713208067, 15739.871148, 1235  
 2122, 281001.745951326, 15289.871148, 1235  
 2123, 281001.898025575, 13199.871148, 1235  
 2124, 281002.154542087, 10666.4911949283, 1235  
 2125, 281002.154542087, 9674.49119492835, 1235  
 2126, 281002.154542087, 8682.49119492835, 1235  
 2127, 281002.411017662, 6149.67384500501, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

2128, 281002.563812825, 4049.76611450588, 1235  
 2129, 281002.596556085, 3599.76611450277, 1235  
 2130, 286001.713208403, 15739.871148, 1235  
 2131, 286001.745951627, 15289.871148, 1235  
 2132, 286001.898025715, 13199.871148, 1235  
 2133, 286002.154541107, 10666.5028573544, 1235  
 2134, 286002.154541107, 9674.50285735437, 1235  
 2135, 286002.154541107, 8682.50285735437, 1235  
 2136, 286002.411017522, 6149.67023216888, 1235  
 2137, 286002.563812295, 4049.76563326053, 1235  
 2138, 286002.59655552, 3599.76563325742, 1235  
 2139, 291001.713208739, 15739.871148, 1235  
 2140, 291001.745951929, 15289.871148, 1235  
 2141, 291001.898025856, 13199.871148, 1235  
 2142, 291002.154540127, 10666.5145197804, 1235  
 2143, 291002.154540127, 9674.51451978039, 1235  
 2144, 291002.154540127, 8682.51451978039, 1235  
 2145, 291002.411017382, 6149.66661933275, 1235  
 2146, 291002.563811766, 4049.76515201518, 1235  
 2147, 291002.596554956, 3599.76515201206, 1235  
 2148, 296001.78113234, 15739.871148, 1235  
 2149, 296001.797503926, 15289.871148, 1235  
 2150, 296001.873540849, 13199.871148, 1235  
 2151, 296002.001797705, 10666.5261818501, 1235  
 2152, 296002.001797705, 9674.52618185014, 1235  
 2153, 296002.001797705, 8682.52618185014, 1235  
 2154, 296002.130036542, 6149.66300669965, 1235  
 2155, 296002.206433636, 4049.76467080422, 1235  
 2156, 296002.222805223, 3599.76467080268, 1235  
 2157, 301001.939754571, 15739.871148, 1235  
 2158, 301001.939754571, 15289.871148, 1235  
 2159, 301001.939754571, 13199.871148, 1235  
 2160, 301001.939754571, 10666.5378441314, 1235  
 2161, 301001.939754571, 9674.53784413144, 1235  
 2162, 301001.939754571, 8682.53784413144, 1235  
 2163, 301001.939754571, 6149.65939400101, 1235  
 2164, 301001.939754571, 4049.76418958453, 1235  
 2165, 301001.939754571, 3599.76418958457, 1235  
 2166, 306002.030453369, 15739.871148, 1235  
 2167, 306002.030453369, 15289.871148, 1235  
 2168, 306002.030453369, 13199.871148, 1235  
 2169, 306002.030453369, 10666.549506769, 1235  
 2170, 306002.030453369, 9674.54950676902, 1235  
 2171, 306002.030453369, 8682.54950676902, 1235  
 2172, 306002.030453369, 6149.65578109934, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

2173, 306002.030453369, 4049.76370833045, 1235  
 2174, 306002.030453369, 3599.76370833048, 1235  
 2175, 311001.87183124, 15739.871148, 1235  
 2176, 311001.88820279, 15289.871148, 1235  
 2177, 311001.964239544, 13199.871148, 1235  
 2178, 311002.092494418, 10666.5611693398, 1235  
 2179, 311002.092494418, 9674.56116933975, 1235  
 2180, 311002.092494418, 8682.56116933975, 1235  
 2181, 311002.220735193, 6149.65216812572, 1235  
 2182, 311002.297131662, 4049.76322705943, 1235  
 2183, 311002.313503212, 3599.76322705788, 1235  
 2184, 316001.71320896, 15739.871148, 1235  
 2185, 316001.745952076, 15289.871148, 1235  
 2186, 316001.898025657, 13199.871148, 1235  
 2187, 316002.154535101, 10666.5728319105, 1235  
 2188, 316002.154535101, 9674.57283191048, 1235  
 2189, 316002.154535101, 8682.57283191048, 1235  
 2190, 316002.41101733, 6149.6485551521, 1235  
 2191, 316002.563810227, 4049.76274578841, 1235  
 2192, 316002.596553343, 3599.76274578529, 1235  
 2193, 321001.713208977, 15739.871148, 1235  
 2194, 321001.745952091, 15289.871148, 1235  
 2195, 321001.898025664, 13199.871148, 1235  
 2196, 321002.154534246, 10666.5844943365, 1235  
 2197, 321002.154534246, 9674.5844943365, 1235  
 2198, 321002.154534246, 8682.5844943365, 1235  
 2199, 321002.411017573, 6149.64494231597, 1235  
 2200, 321002.563810235, 4049.76226454305, 1235  
 2201, 321002.596553348, 3599.76226453993, 1235  
 2202, 326075.356551507, 15739.871148, 1235  
 2203, 326075.372923055, 15289.871148, 1235  
 2204, 326075.448959801, 13199.871148, 1235  
 2205, 326075.577213813, 10666.5963280198, 1235  
 2206, 326075.577213813, 9674.59632801983, 1235  
 2207, 326075.577213813, 8682.59632801983, 1235  
 2208, 326075.705455686, 6149.64127651968, 1235  
 2209, 326075.781851919, 4049.76177625053, 1235  
 2210, 326075.798223467, 3599.76177624898, 1235  
 2211, 331209.005432856, 15739.871148, 1235  
 2212, 331209.00643821, 15289.871148, 1235  
 2213, 331209.01110752, 13199.871148, 1235  
 2214, 331209.018983367, 10666.6083016968, 1235  
 2215, 331209.018983367, 9674.60830169681, 1235  
 2216, 331209.018983367, 8682.60830169681, 1235  
 2217, 331209.026858591, 6149.63756734988, 1235

## PROJECT TITLE :

|                                                                                   |         |     |           |          |
|-----------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                   | Author  | g60 | File Name | 노변교 (부산) |

2218, 331209.031549963, 4049.76128218002, 1235  
 2219, 331209.032555317, 3599.76128217994, 1235  
 2220, 336329.052659942, 15739.871148, 1235  
 2221, 336329.053665296, 15289.871148, 1235  
 2222, 336329.058334606, 13199.871148, 1235  
 2223, 336329.066210453, 10666.6202441312, 1235  
 2224, 336329.066210453, 9674.62024413121, 1235  
 2225, 336329.066210453, 8682.62024413121, 1235  
 2226, 336329.074085677, 6149.63386777156, 1235  
 2227, 336329.078777049, 4049.76078938023, 1235  
 2228, 336329.079782403, 3599.76078938015, 1235  
 2229, 341448.903778962, 15739.871148, 1235  
 2230, 341448.920150472, 15289.871148, 1235  
 2231, 341448.996187041, 13199.871148, 1235  
 2232, 341449.124439014, 10666.6321865913, 1235  
 2233, 341449.124439014, 9674.63218659127, 1235  
 2234, 341449.124439014, 8682.63218659127, 1235  
 2235, 341449.252682867, 6149.63016809831, 1235  
 2236, 341449.329078455, 4049.7602965609, 1235  
 2237, 341449.345449966, 3599.76029655933, 1235  
 2238, 346568.713210056, 15739.871148, 1235  
 2239, 346568.745953058, 15289.871148, 1235  
 2240, 346568.898026114, 13199.871148, 1235  
 2241, 346569.154529485, 10666.6441289857, 1235  
 2242, 346569.154529485, 9674.6441289857, 1235  
 2243, 346569.154529485, 8682.6441289857, 1235  
 2244, 346569.411017623, 6149.62646843971, 1235  
 2245, 346569.563808599, 4049.75980374306, 1235  
 2246, 346569.596551602, 3599.75980373992, 1235  
 2247, 351688.7132104, 15739.871148, 1235  
 2248, 351688.745953367, 15289.871148, 1235  
 2249, 351688.898026258, 13199.871148, 1235  
 2250, 351689.154528482, 10666.6560713099, 1235  
 2251, 351689.154528482, 9674.65607130995, 1235  
 2252, 351689.154528482, 8682.65607130995, 1235  
 2253, 351689.411017479, 6149.62276889551, 1235  
 2254, 351689.563808056, 4049.75931094782, 1235  
 2255, 351689.596551023, 3599.75931094468, 1235  
 2256, 356808.713210744, 15739.871148, 1235  
 2257, 356808.745953676, 15289.871148, 1235  
 2258, 356808.898026402, 13199.871148, 1235  
 2259, 356809.154527478, 10666.6680136342, 1235  
 2260, 356809.154527478, 9674.66801363419, 1235  
 2261, 356809.154527478, 8682.66801363419, 1235  
 2262, 356809.411017335, 6149.61906935131, 1235

## PROJECT TITLE :

|                                                                                     |         |     |           |          |
|-------------------------------------------------------------------------------------|---------|-----|-----------|----------|
|  | Company |     | Client    |          |
|                                                                                     | Author  | g60 | File Name | 노변교 (부산) |

2263, 356809.563807514, 4049.75881815258, 1235  
 2264, 356809.596550445, 3599.75881814944, 1235  
 2265, 361928.713211089, 15739.871148, 1235  
 2266, 361928.745953984, 15289.871148, 1235  
 2267, 361928.898026545, 13199.871148, 1235  
 2268, 361929.154526475, 10666.6799559584, 1235  
 2269, 361929.154526475, 9674.67995595843, 1235  
 2270, 361929.154526475, 8682.67995595843, 1235  
 2271, 361929.411017192, 6149.61536980712, 1235  
 2272, 361929.563806971, 4049.75832535733, 1235  
 2273, 361929.596549867, 3599.75832535419, 1235  
 2274, 367048.713211433, 15739.871148, 1235  
 2275, 367048.745954293, 15289.871148, 1235  
 2276, 367048.898026689, 13199.871148, 1235  
 2277, 367049.154525471, 10666.6918982827, 1235  
 2278, 367049.154525471, 9674.69189828268, 1235  
 2279, 367049.154525471, 8682.69189828268, 1235  
 2280, 367049.411017048, 6149.61167026292, 1235  
 2281, 367049.563806428, 4049.75783256209, 1235  
 2282, 367049.596549288, 3599.75783255895, 1235  
 2283, 372168.713211777, 15739.871148, 1235  
 2284, 372168.745954602, 15289.871148, 1235  
 2285, 372168.898026833, 13199.871148, 1235  
 2286, 372169.154524468, 10666.7038406069, 1235  
 2287, 372169.154524468, 9674.70384060692, 1235  
 2288, 372169.154524468, 8682.70384060692, 1235  
 2289, 372169.411016904, 6149.60797071872, 1235  
 2290, 372169.563805885, 4049.75733976685, 1235  
 2291, 372169.59654871, 3599.7573397637, 1235  
 2292, 377291.213212121, 15739.871148, 1235  
 2293, 377291.24595491, 15289.871148, 1235  
 2294, 377291.398026976, 13199.871148, 1235  
 2295, 377291.654523464, 10666.7157887624, 1235  
 2296, 377291.654523464, 9674.71578876238, 1235  
 2297, 377291.654523464, 8682.71578876238, 1235  
 2298, 377291.911016761, 6149.60426936811, 1235  
 2299, 377292.063805342, 4049.75684673098, 1235  
 2300, 377292.096548132, 3599.75684672783, 1235  
 2301, 382416.356553081, 15739.871148, 1235  
 2302, 382416.372924467, 15289.871148, 1235  
 2303, 382416.448960458, 13199.871148, 1235  
 2304, 382416.577208415, 10666.7277425687, 1235  
 2305, 382416.577208415, 9674.72774256872, 1235  
 2306, 382416.577208415, 8682.72774256872, 1235  
 2307, 382416.705455279, 6149.60056635961, 1235