




5. 부용1고가(B34)



위치	13 SPAN -5	선별	T2	부위	TCL
내용	균열	Cw= 0.5/0.1			




위치	24 SPAN -3	선별	T1	부위	TCL
내용	균열	Cw= 0.4/0.5			




위치	27 SPAN -2	선별	T2	부위	TCL
내용	균열	Cw= 0.4/0.4			



위치	30 SPAN -2	선별	T1	부위	TCL
내용	균열	Cw= 1.0/0.2			



위치	32 SPAN -2	선별	T1	부위	TCL
내용	균열	Cw= 0.4/0.2			




위치	32 SPAN -3	선별	T1	부위	TCL
내용	균열	Cw= 1.0/0.7			




위치	32 SPAN -4	선별	T1	부위	TLC
내용	균열	Cw= 0.4/0.3			




위치	42 SPAN -1	선별	T2	부위	TCL
내용	균열	Cw= 0.4/0.3			



위치	42 SPAN -2	선별	T1	부위	TLC
내용	균열	Cw= 0.6/0.2			



위치	42 SPAN -2	선별	T2	부위	TLC
내용	균열	Cw= 0.5/0.6			




위치	61 SPAN 4	선별	T2	부위	TCL
내용	균열	Cw= 0.5/0.1			




위치	20 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.3/0.3			




위치	20 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.3/0.3			




위치	21 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	21 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			



위치	22 SPAN -1	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	22 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.2			



위치	22 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	23 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	23 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.3			



위치	24 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			



위치	24 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	24 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	24 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	24 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	24 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			



위치	24 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	24 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	24 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	24 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	24 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	24 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	25 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	25 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	25 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	25 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			



위치	25 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			



위치	26 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.4			




위치	26 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			



위치	26 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			



위치	26 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			



위치	27 SPAN -2	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.2			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			




위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	27 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	30 SPAN -1	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	30 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.7			




위치	30 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.4			




위치	30 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.4			



위치	30 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.4			



위치	30 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	30 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	33 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			



위치	33 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	33 SPAN -4	선별	T1	부위	침목	위치	34 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4				내용	경계부 균열	Cw= 0.4/0.4			




위치	34 SPAN -4	선별	T1	부위	침목	위치	34 SPAN -4	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.9				내용	경계부 균열	Cw= 0.5/0.4			



위치	35 SPAN -5	선별	T1	부위	침목	위치	36 SPAN -1	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4				내용	경계부 균열	Cw= 0.4/0.4			



위치	40 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			




위치	42 SPAN -2	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	42 SPAN -2	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.3/2.3			



위치	42 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			



위치	42 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			



위치	42 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			



위치	42 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	42 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	42 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/2.3			




위치	42 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			




위치	43 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			



위치	43 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	43 SPAN -5	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			



위치	43 SPAN -5	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.3			



위치	43 SPAN -5	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	44 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	44 SPAN -1	선별	2T	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	44 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			



위치	44 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.3/0.5			



위치	46 SPAN -1	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.4			




위치	46 SPAN -1	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.4			



위치	46 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.5			



위치	46 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.5			



위치	46 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.5			



위치	46 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.5			




위치	46 SPAN -1	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.5			




위치	46 SPAN -2	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.9			




위치	46 SPAN -3	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.5/0.9			




위치	46 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.5			




위치	46 SPAN -3	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4			



위치	46 SPAN -4	선별	T2	부위	침목	위치	46 SPAN -4	선별	T2	부위	침목
내용	경계부 균열	Cw= 0.5/0.4				내용	경계부 균열	Cw= 0.5/0.4			



위치	47 SPAN -1	선별	T1	부위	침목	위치	47 SPAN -1	선별	T1	부위	침목
내용	경계부 균열	Cw= 0.4/0.9				내용	경계부 균열	Cw= 0.4/0.4			



위치	49 SPAN -5	선별	T1	부위	침목	위치	1 SPAN -5	선별	T1	부위	TCL
내용	경계부 균열	Cw= 0.5/0.4				내용	파손	A= 0.3X0.1			




위치	3 SPAN -2	선별	T1	부위	TCL
내용	파손	A= 0.1X0.1			




위치	3 SPAN -3	선별	T1	부위	TCL
내용	파손	A= 0.1X0.1			




위치	3 SPAN -4	선별	T1	부위	TCL
내용	파손	A= 0.1X0.2			




위치	3 SPAN -4	선별	T1	부위	TCL
내용	파손	A= 0.1X0.1			




위치	6 SPAN -5	선별	T1	부위	TCL
내용	파손	A= 0.1X0.1			




위치	6 SPAN -5	선별	T1	부위	TCL
내용	파손	A= 0.1X0.1			



위치	6 SPAN -5	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.2			



위치	6 SPAN -5	선별	T1	부위	TCL
내용	파손	A= 0.1X0.2			



위치	7 SPAN -1	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.4			



위치	7 SPAN -2	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.2			



위치	7 SPAN -2	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.1			



위치	7 SPAN -2	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.1			



위치	8 SPAN -3	선별	T2	부위	TCL
내용	박락	A= 0.1X0.2			



위치	10 SPAN -2	선별	T1	부위	TCL
내용	파손	A= 0.1X0.1			



위치	11 SPAN -2	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.1			



위치	16 SPAN -1	선별	T1	부위	TCL
내용	재료분리	A= 0.2X0.5			



위치	21 SPAN -3	선별	T1	부위	TCL
내용	재료분리	A= 0.2X0.1			



위치	23 SPAN -2	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.4			