

호남고속선 화물고가 _106(17.621~17.629, S20-1)

P19

17K621

17K629

20 SPAN - 1

PCL상면	TCL상면	TCL측면
TM 278.3	TM 102.2	15.0, 2/0.3 (12) 15.0, 2/0.3 (13) 15.0, 2/0.4 (14) 15.0, 2/0.3 (15) 16.0, 1/0.3
13		
12		
11		
10		
9		
8		
7		
6		
5		
4		
3		
2		
1		
15.0, 1/0.2	15.0, 2/0.4	15.0, 2/0.4

$$\begin{pmatrix} \text{아} \\ \text{아} \end{pmatrix}$$
$$\begin{pmatrix} \text{아} \\ \text{아} \end{pmatrix}$$

채움콘크리트

12 (앞 0주)

(수원)

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.2	0.4 m		56	균열	0.2	0.4 m	
2	균열	0.2	mm	0.4 m	57	균열	0.1	mm	0.3 m
3	균열	0.2	mm	0.4 m	58	균열	0.2	mm	0.4 m
4	균열	0.1	mm	0.5 m	59	균열	0.2	mm	
5	균열	0.2	mm	0.6 m	60				
6	균열	0.2	mm	0.3 m	61				
7	균열	0.2	mm	0.4 m	62				
8	균열	0.2	mm	0.4 m	63				
9	균열	0.2	mm	0.7 m	64				
10	균열	0.2	mm	0.4 m	65				
11	균열	0.1	mm	0.2 m	66				
12	경계부 균열	0.2	mm	0.3 m	67				
13	균열	0.2	mm	0.4 m	68				
14	균열	0.1	mm	0.5 m	69				
15	경계부 균열	0.2	mm	0.3 m	70				
16	균열	0.2	mm	0.4 m	71				
17	균열	0.2	mm	0.4 m	72				
18	균열	0.1	mm	0.3 m	73				
19	균열	0.1	mm	0.2 m	74				
20	균열	0.2	mm	0.0 m	75				
21	균열	0.1	mm	0.5 m	76				
22	균열	0.2	mm	0.5 m	77				
23	균열	0.1	mm	0.8 m	78				
24	균열	0.1	mm	0.3 m	79				
25	균열	0.2	mm	0.4 m	80				
26	균열	0.2	mm	0.4 m	81				
27	균열	0.2	mm	0.4 m	82				
28	균열	0.2	mm	0.4 m	83				
29	균열	0.2	mm	0.4 m	84				
30	균열	0.2	mm	0.6 m	85				
31	균열	0.1	mm	0.4 m	86				
32	균열	0.2	mm	0.8 m	87				
33	균열	0.2	mm	0.4 m	88				
34	균열	0.2	mm	0.4 m	89				
35	균열	0.2	mm	0.4 m	90				
36	균열	0.1	mm	0.6 m	91				
37	균열	0.2	mm	0.3 m	92				
38	균열	0.1	mm	0.4 m	93				
39	균열	0.2	mm	0.6 m	94				
40	균열	0.2	mm	0.4 m	95				
41	균열	0.1	mm	0.4 m	96				
42	균열	0.2	mm	0.6 m	97				
43	균열	0.2	mm	0.4 m	98				
44	균열	0.1	mm	0.6 m	99				
45	균열	0.2	mm	0.2 m	100				
46	균열	0.2	mm	0.4 m	101				
47	균열	0.1	mm	0.4 m	102				
48	균열	0.2	mm	0.6 m	103				
49	균열	0.2	mm	0.4 m	104				
50	균열	0.2	mm	0.4 m	105				
51	균열	0.2	mm	0.4 m	106				
52	균열	0.2	mm	0.4 m	107				
53	방수균열	2.2 m	0.1 m	0.22	108				
54	균열	0.1	mm	0.5 m	109				
55	균열	0.1	mm	0.3 m	110				

[illegible]