


호남고속선 호암교_91(46.949~46.956km, S18-5)

P18

46K956

18 SPAN - 5

46K949



(아
0호)


(아
호)

TCL상면
TCL측면

TCL集团


HSB 銀行

HSB 2017



TCL상면

TCL상면



12 (유안)

(유아)

TCL 상면	TCL 추면
--------	--------

TCL集团

HSB상단 배

HSB 銀行

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.1 mm	0.4 m			56				
2	균열 0.1 mm	0.65 m			57				
3	균열 0.3 mm	0.3 m			58				
4	균열 0.1 mm	0.3 m			59				
5	균열 0.1 mm	0.3 m			60				
6	균열 0.1 mm	0.65 m			61				
7	균열 0.1 mm	0.7 m			62				
8	균열 0.1 mm	0.66 m			63				
9	균열 0.1 mm	0.3 m			64				
10	균열 0.1 mm	0.4 m			65				
11	균열 0.1 mm	0.3 m			66				
12	균열 0.1 mm	0.4 m			67				
13	균열 0.1 mm	0.3 m			68				
14	균열 0.1 mm	0.4 m			69				
15	균열 0.1 mm	0.3 m			70				
16	균열 0.1 mm	0.7 m			71				
17	균열 0.1 mm	0.7 m			72				
18	균열 0.1 mm	0.7 m			73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

[illegible]