

호남고속선장구교_37(48.747~48.754km, S8-1)

P7

48K747

48K754

8 SPAN - 1

PCL상 [M]

—

TCL	TCL상
-----	------

10	10
10	10

TM.085.4

TM.084.2

[illegible]

二

(후보)

1
2
3
4
5
6
7
8
9
10
11

TCL상면	TCL측면
-------	-------

PCL 상용

—

② 16-0.2/0.6

TCL측면	TCL상면
-------	-------

1	2
3	4

TM.049.3

TM.243.4

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	

T2 (후보)

(07010)

[illegible]

TCL상면	TCL측면
-------	-------

PCL 5th 版

☐

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m		55				
2	균열	0.2 mm	0.6 m		56				
3					57				
4					58				
5					59				
6					60				
7					61				
8					62				
9					63				
10					64				
11					65				
12					66				
13					67				
14					68				
15					69				
16					70				
17					71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]