




□ 단양대교(부산) 신축이음장치 점검결과

위 치	점 검 결 과				
A1	1	2	3	4	5
					
	전 경 (상 부)	일평균기온:26.3℃ 신축이음유간:13.0cm	일평균기온:17.0℃ 신축이음유간:15.0cm	일평균기온:26.3℃ 바닥판단부:43.0cm	일평균기온:17.0℃ 바닥판단부:45.0cm
A2	1	2	3	4	5
					
	전 경 (상 부)	일평균기온:26.3℃ 신축이음유간:11.0cm	일평균기온:17.0℃ 신축이음유간:13.0cm	일평균기온:26.3℃ 바닥판단부:31.0cm	일평균기온:17.0℃ 바닥판단부:32.0cm

□ 단양대교(부산) 교량반침 점검결과

위 치	점 검 결 과				
A1 SH-1	1	2	3	4	5
					
	전 경	일평균기온:27.6℃ 이동량: A2 4.5cm	일평균기온:17.0℃ 이동량: A2 5.0cm	연단거리: A2(52cm)	
A1 SH-2	1	2	3	4	5
					
	전 경	일평균기온:27.6℃ 이동량: A2 4.5cm	일평균기온:17.0℃ 이동량: A2 5.0cm	연단거리: A2(52cm)	
P1 SH-1	1	2	3	4	5
					
	전 경	일평균기온:27.6℃ 이동량: A2 1.0cm	일평균기온:17.0℃ 이동량: A2 1.5cm	연단거리: A1(430cm) 연단거리: A2(430cm)	
P1 SH-2	1	2	3	4	5
					
	전 경	일평균기온:27.6℃ 이동량: A2 0.5cm	일평균기온:17.0℃ 이동량: A2 1.0cm	연단거리: A1(430cm) 연단거리: A2(430cm)	
A2 SH-1	1	2	3	4	5
					
	전 경	일평균기온:27.6℃ 이동량: A1 4.5cm	일평균기온:17.0℃ 이동량: A1 5.0cm	연단거리: A1(77cm) 연단거리: A2(77cm)	

위 치	점 검 결 과				
A2 SH-2	1	2	3	4	5
					
	전 경	일평균기온:27.6℃ 이동량: A1 4.5cm	일평균기온:17.0℃ 이동량: A1 5.0cm	연단거리: A1(78cm) 연단거리: A2(78cm)	