

2. 받침장치 전수조사

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
A1-01	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:6.0mm			
A1-02	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:6.0mm			
A1-03	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:6.0mm			
A1-04	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:6.0mm			
A1-05	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:6.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
A2-01	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:10.0mm			
A2-02	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:10.0mm			
A2-03	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:10.0mm			
A2-04	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:10.0mm			
A2-05	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:10.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P1-01 A1측	1	2	3	4	5
					
	전경	고정단			
P1-02 A1측	1	2	3	4	5
					
	전경	고정단			
P1-03 A1측	1	2	3	4	5
					
	전경	고정단			
P1-04 A1측	1	2	3	4	5
					
	전경	고정단			
P1-05 A1측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P1-01 A2측	1	2	3	4	5
					
	전경	고정단			
P1-02 A2측	1	2	3	4	5
					
	전경	고정단			
P1-03 A2측	1	2	3	4	5
					
	전경	고정단			
P1-04 A2측	1	2	3	4	5
					
	전경	고정단			
P1-05 A2측	1	2	3	4	5
					
	전경	고정단			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P2-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:5.0mm			
P2-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:5.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치		점 검 결 과			
P2-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P2-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P3-01 A1측	1	2	3	4	5
					
	전경	고정단			
P3-02 A1측	1	2	3	4	5
					
	전경	고정단			
P3-03 A1측	1	2	3	4	5
					
	전경	고정단			
P3-04 A1측	1	2	3	4	5
					
	전경	고정단			
P3-05 A1측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P3-01 A2측	1	2	3	4	5
					
	전경	고정단			
P3-02 A2측	1	2	3	4	5
					
	전경	고정단			
P3-03 A2측	1	2	3	4	5
					
	전경	고정단			
P3-04 A2측	1	2	3	4	5
					
	전경	고정단			
P3-05 A2측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P4-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P4-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P4-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			
P4-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			
P4-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:3.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치		점 검 결 과				
P4-01 A2측	1	2	3	4	5	
						
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm				
P4-02 A2측	1	2	3	4	5	
						
	전경	평균기온:19.7℃ 이동량 A2측:5.0mm				
P4-03 A2측	1	2	3	4	5	
						
	전경	평균기온:19.7℃ 이동량 A2측:5.0mm				
P4-04 A2측	1	2	3	4	5	
						
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm				
P4-05 A2측	1	2	3	4	5	
						
	전경	평균기온:19.7℃ 이동량 A2측:4.5mm				

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P5-01 A1측	1	2	3	4	5
					
	전경	고정단			
P5-02 A1측	1	2	3	4	5
					
	전경	고정단			
P5-03 A1측	1	2	3	4	5
					
	전경	고정단			
P5-04 A1측	1	2	3	4	5
					
	전경	고정단			
P5-05 A1측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P5-01 A2측	1	2	3	4	5
					
	전경	고정단			
P5-02 A2측	1	2	3	4	5
					
	전경	고정단			
P5-03 A2측	1	2	3	4	5
					
	전경	고정단			
P5-04 A2측	1	2	3	4	5
					
	전경	고정단			
P5-05 A2측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P6-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:2.0mm			
P6-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:2.0mm			
P6-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P6-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P6-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P6-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P6-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P6-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P6-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P6-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P7-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.5mm			
P7-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.5mm			
P7-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P7-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:3.0mm			
P7-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:2.5mm			



□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P7-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.5mm			
P7-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.5mm			
P7-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm			
P7-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:5.5mm			
P7-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:6.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P8-01 A1측	1	2	3	4	5
					
	전경	고정단			
P8-02 A1측	1	2	3	4	5
					
	전경	고정단			
P8-03 A1측	1	2	3	4	5
					
	전경	고정단			
P8-04 A1측	1	2	3	4	5
					
	전경	고정단			
P8-05 A1측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P8-01 A2측	1	2	3	4	5
					
	전경	고정단			
P8-02 A2측	1	2	3	4	5
					
	전경	고정단			
P8-03 A2측	1	2	3	4	5
					
	전경	고정단			
P8-04 A2측	1	2	3	4	5
					
	전경	고정단			
P8-05 A2측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P9-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P9-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P9-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P10-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:7.0mm			
P10-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm			
P10-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm			
P10-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm			
P10-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.5mm			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P10-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:4.0mm			
P10-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P10-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P10-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P10-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:3.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P11-01 A1측	1	2	3	4	5
					
	전경	고정단			
P11-02 A1측	1	2	3	4	5
					
	전경	고정단			
P11-03 A1측	1	2	3	4	5
					
	전경	고정단			
P11-04 A1측	1	2	3	4	5
					
	전경	고정단			
P11-05 A1측	1	2	3	4	5
					
	전경	고정단			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P11-01 A2측	1	2	3	4	5
					
	전경	고정단			
P11-02 A2측	1	2	3	4	5
					
	전경	고정단			
P11-03 A2측	1	2	3	4	5
					
	전경	고정단			
P11-04 A2측	1	2	3	4	5
					
	전경	고정단			
P11-05 A2측	1	2	3	4	5
					
	전경	고정단			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P12-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:1.0mm			
P12-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:2.0mm			
P12-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:1.0mm			
P12-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:1.0mm			
P12-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:1.0mm			

장천교(여주) 교량반침 점검결과

위 치	점 검 결 과				
P12-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P12-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:2.0mm			
P12-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P12-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			
P12-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:1.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P13-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			
P13-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			
P13-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			
P13-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			
P13-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:5.0mm			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P13-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:7.0mm			
P13-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:7.0mm			
P13-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:7.0mm			
P13-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:7.0mm			
P13-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A2측:7.0mm			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P14-01 A1측	1	2	3	4	5
					
	전경	고정단			
P14-02 A1측	1	2	3	4	5
					
	전경	고정단			
P14-03 A1측	1	2	3	4	5
					
	전경	고정단			
P14-04 A1측	1	2	3	4	5
					
	전경	고정단			
P14-05 A1측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P14-01 A2측	1	2	3	4	5
					
	전경	고정단			
P14-02 A2측	1	2	3	4	5
					
	전경	고정단			
P14-03 A2측	1	2	3	4	5
					
	전경	고정단			
P14-04 A2측	1	2	3	4	5
					
	전경	고정단			
P14-05 A2측	1	2	3	4	5
					
	전경	고정단			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P15-01 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P15-02 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P15-03 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P15-04 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			
P15-05 A1측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:4.0mm			


□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P15-01 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:11.0mm			
P15-02 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:11.0mm			
P15-03 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:11.0mm			
P15-04 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:11.0mm			
P15-05 A2측	1	2	3	4	5
					
	전경	평균기온:19.7℃ 이동량 A1측:11.0mm			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P16-01 A1측	1	2	3	4	5
					
	전경	고정단			
P16-02 A1측	1	2	3	4	5
					
	전경	고정단			
P16-03 A1측	1	2	3	4	5
					
	전경	고정단			
P16-04 A1측	1	2	3	4	5
					
	전경	고정단			
P16-05 A1측	1	2	3	4	5
					
	전경	고정단			

□ 장천교(여주) 교량받침 점검결과

위 치	점 검 결 과				
P16-01 A2측	1	2	3	4	5
					
	전경	고정단			
P16-02 A2측	1	2	3	4	5
					
	전경	고정단			
P16-03 A2측	1	2	3	4	5
					
	전경	고정단			
P16-04 A2측	1	2	3	4	5
					
	전경	고정단			
P16-05 A2측	1	2	3	4	5
					
	전경	고정단			