

신김포-신파주

Station(m)	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	결함점수 합계	결함지수
0~20	3.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	3	0.088
20~40	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
40~60	5.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
60~80	4.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	4	0.118
80~100	4.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	4	0.118
100~120	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
120~140	3.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	3	0.088
140~160	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
160~180	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
180~200	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
200~220	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
220~240	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
240~260	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
260~280	2.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	2	0.059
280~300	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
300~320	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	6	0.176
320~340	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
340~360	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
360~380	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
380~400	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
400~420	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
420~440	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
440~460	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
460~480	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
480~500	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
500~520	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
520~540	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
540~560	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
560~580	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
580~600	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
600~620	5.00	0.01	1.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
620~640	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
640~660	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
660~680	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
680~700	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
700~720	6.00	0.01	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
720~740	5.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
740~760	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
760~780	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
780~800	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
800~820	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
820~840	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
840~860	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
860~880	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
880~900	5.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	0	5	0.147
900~920	0.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
920~940	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
940~960	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
960~980	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
980~1000	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
1000~1020	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1020~1040	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
Station(m)	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	결함점수 합계	결함지수

1040~1060	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1060~1080	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1080~1100	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1100~1120	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1120~1140	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1140~1160	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1160~1180	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1180~1200	5.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
1200~1220	6.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1220~1240	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1240~1260	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1260~1280	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1280~1300	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1300~1320	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1320~1340	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1340~1360	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
1360~1380	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1380~1400	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1400~1420	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1420~1440	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1440~1460	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1460~1480	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1480~1500	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1500~1520	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
1520~1540	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1540~1560	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1560~1580	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	5	0.147
1580~1600	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1600~1620	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1620~1640	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
1640~1660	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
1660~1680	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1680~1700	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1700~1720	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1720~1740	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1740~1760	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1760~1780	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1780~1800	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
1800~1820	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	0	5	0.147
1820~1840	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147

1840~1860	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1860~1880	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1880~1900	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
1900~1920	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
1920~1940	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1940~1960	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1960~1980	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
1980~2000	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
2000~2020	4.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	4	0.118
2020~2040	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2040~2060	4.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	4	0.118
2060~2080	4.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	4	0.118
2080~2100	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2100~2120	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
Station(m)	균열	누수	파손 및 손 상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	결함점수 합계	결함지수
2120~2140	0.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2140~2160	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
2160~2180	0.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2180~2200	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2200~2220	4.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	4	0.118
2220~2240	0.00	0.01	0.00	0.01	0.00	0.01	0.00	0.00	x	0	0.000
2240~2260	4.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	4	0.118
2260~2280	6.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
2280~2300	5.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
2300~2320	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
2320~2340	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
2340~2360	4.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	4	0.118
2360~2380	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2380~2400	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	0	0.000
2400~2420	3.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	3	0.088
2420~2440	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
2440~2460	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
2460~2480	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2480~2500	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2500~2520	3.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	3	0.088
2520~2540	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
2540~2560	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.01	x	0	0.000
2560~2580	3.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	3	0.088
2580~2600	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2600~2620	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000

2620~2640	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
2640~2660	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
2660~2680	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2680~2700	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2700~2720	0.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2720~2740	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2740~2760	5.00	0.01	0.00	0.00	0.00	1.00	0.00	0.00	x	6	0.176
2760~2780	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2780~2800	0.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	1	0.029
2800~2820	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2820~2840	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2840~2860	3.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	3	0.088
2860~2880	3.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	3	0.088
2880~2900	0.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
2900~2920	3.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	3	0.088
2920~2940	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2940~2960	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2960~2980	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2980~3000	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3000~3020	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3020~3040	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3040~3060	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3060~3080	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3080~3100	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3100~3120	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3120~3140	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3140~3160	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3160~3180	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3180~3200	0.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
Station(m)	균열	누수	파손 및 손 상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	결함점수 합계	결함지수
3200~3220	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3220~3240	5.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
3240~3260	3.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	3	0.088
3260~3280	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	0	0.000
3280~3300	0.00	0.00	0.01	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3300~3320	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3320~3340	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3340~3360	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
3360~3380	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
3380~3400	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147

3400~3420	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
3420~3440	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
3440~3460	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3460~3480	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3480~3500	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3500~3520	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
3520~3540	5.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3540~3560	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3560~3580	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3580~3600	0.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	0	0.000
3600~3620	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3620~3640	3.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	3	0.088
3640~3660	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3660~3680	5.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	6	0.176
3680~3700	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
3700~3720	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
3720~3740	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
3740~3760	5.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
3760~3780	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
3780~3800	5.00	0.01	0.00	0.00	0.00	1.00	0.00	0.00	x	6	0.176
3800~3820	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3820~3840	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3840~3860	3.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	3	0.088
3860~3880	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3880~3900	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3900~3920	4.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	5	0.147
3920~3940	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3940~3960	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3960~3980	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	5	0.147
3980~4000	4.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	4	0.118
4000~4020	4.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	4	0.118
4020~4040	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
4040~4060	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
4060~4080	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
4080~4100	4.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	4	0.118
4100~4120	3.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	3	0.088
4120~4140	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
4140~4160	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
4160~4180	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
4180~4200	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	0	0.000
Station(m)	구역	누수	파손 및손	바리	충분리 및	배터	재료	철근	타사하	결합점수	경하지수

[illegible][illegible]

980~1000	b	a	a	a	a	b	a	a	x	a
1000~1020	a	a	a	a	a	a	a	a	x	a
1020~1040	b	a	a	a	a	a	a	a	x	a
1040~1060	c	a	a	a	a	b	a	a	x	b
1060~1080	a	a	a	a	a	a	a	a	x	a
1080~1100	a	a	a	a	a	a	a	a	x	a
1100~1120	b	a	a	a	a	a	a	a	x	a
1120~1140	b	a	a	a	a	a	a	a	x	a
1140~1160	c	a	a	a	a	a	a	a	x	b
1160~1180	b	a	a	a	a	a	a	a	x	a
1180~1200	b	a	a	a	a	b	a	a	x	a
1200~1220	c	a	a	a	a	a	a	a	x	b
1220~1240	a	a	a	a	a	a	a	a	x	a
1240~1260	a	a	a	a	a	a	a	a	x	a
1260~1280	a	a	a	a	a	a	a	a	x	a
1280~1300	c	a	a	a	a	a	a	a	x	b
1300~1320	b	a	a	a	a	a	a	a	x	a
1320~1340	b	a	a	a	a	a	a	a	x	a
1340~1360	b	a	a	a	a	b	a	a	x	a
1360~1380	b	a	a	a	a	a	a	a	x	a
1380~1400	b	a	a	a	a	a	a	a	x	a
1400~1420	c	a	a	a	a	a	a	a	x	b
1420~1440	a	a	a	a	a	a	a	a	x	a
1440~1460	b	a	a	a	a	a	a	a	x	a
1460~1480	c	a	a	a	a	b	a	a	x	b
1480~1500	b	a	a	a	a	a	a	a	x	a
1500~1520	b	a	a	a	a	b	a	a	x	a
1520~1540	c	a	a	a	a	a	a	a	x	b
1540~1560	b	a	a	a	a	a	a	a	x	a
1560~1580	b	a	a	a	a	a	a	a	a	a
1580~1600	b	a	a	a	a	a	a	a	x	a
1600~1620	b	a	a	a	a	a	a	a	x	a
1620~1640	a	a	a	a	a	b	a	a	x	a
1640~1660	b	a	a	a	a	b	a	a	x	a
1660~1680	b	a	a	a	a	a	a	a	x	a
1680~1700	b	a	a	a	a	a	a	a	x	a
1700~1720	a	a	a	a	a	a	a	a	x	a
1720~1740	b	a	a	a	a	a	a	a	x	a
1740~1760	b	a	a	a	a	a	a	a	x	a
1760~1780	a	a	a	a	a	a	a	a	x	a
1780~1800	b	a	a	a	a	b	a	a	x	a

1800~1820	b	a	a	a	a	b	a	a	a	a
1820~1840	b	a	a	a	a	a	a	a	x	a
1840~1860	b	a	a	a	a	a	a	a	x	a
1860~1880	b	a	a	a	a	a	a	a	x	a
1880~1900	a	a	a	a	a	a	a	a	x	a
1900~1920	a	a	a	a	a	b	a	a	x	a
1920~1940	b	a	a	a	a	a	a	a	x	a
1940~1960	b	a	a	a	a	a	a	a	x	a
1960~1980	b	a	a	a	a	a	a	a	x	a
1980~2000	b	a	a	a	a	a	a	a	x	a
Station(m)	균열	누수	파손 및 손상	박리	층분리 및 박락	백태	재료 분리	철근 노출	탄산화	상태평가 결과
2000~2020	b	a	a	a	a	b	a	a	x	a
2020~2040	a	a	a	a	a	a	a	a	x	a
2040~2060	b	a	a	a	a	b	a	a	x	a
2060~2080	b	a	a	a	a	b	a	a	x	a
2080~2100	a	a	a	a	a	a	a	a	x	a
2100~2120	a	a	a	a	a	a	a	a	x	a
2120~2140	a	a	a	a	a	a	a	a	x	a
2140~2160	c	a	a	a	a	a	a	a	x	b
2160~2180	a	a	a	a	a	a	a	a	x	a
2180~2200	a	a	a	a	a	a	a	a	x	a
2200~2220	b	a	a	a	a	b	a	a	x	a
2220~2240	a	a	a	b	a	b	a	a	x	a
2240~2260	b	a	a	a	a	b	a	a	x	a
2260~2280	c	a	a	a	a	a	a	a	x	b
2280~2300	b	a	a	a	a	b	a	a	x	a
2300~2320	b	a	a	a	a	a	a	a	x	a
2320~2340	a	a	a	a	a	b	a	a	x	a
2340~2360	b	a	a	a	a	b	a	a	x	a
2360~2380	a	a	a	a	a	a	a	a	x	a
2380~2400	a	a	a	a	a	a	a	a	a	a
2400~2420	b	a	a	a	a	a	a	a	x	a
2420~2440	b	a	a	a	a	a	a	a	x	a
2440~2460	b	a	a	a	a	a	a	a	x	a
2460~2480	a	a	a	a	a	a	a	a	x	a
2480~2500	a	a	a	a	a	a	a	a	x	a
2500~2520	b	a	a	a	a	a	a	a	x	a
2520~2540	a	a	a	a	a	b	a	a	x	a
2540~2560	a	a	a	a	a	a	a	a	x	a
2560~2580	b	a	a	a	a	b	a	a	x	a

2580~2600	a	a	a	a	a	a	a	a	x	a
2600~2620	a	a	a	a	a	a	a	a	x	a
2620~2640	a	a	a	a	a	b	a	a	x	a
2640~2660	b	a	a	a	a	b	a	a	x	a
2660~2680	a	a	a	a	a	a	a	a	x	a
2680~2700	a	a	a	a	a	a	a	a	x	a
2700~2720	a	a	a	a	a	a	a	a	x	a
2720~2740	a	a	a	a	a	a	a	a	x	a
2740~2760	b	a	a	a	a	c	a	a	x	b
2760~2780	a	a	a	a	a	a	a	a	x	a
2780~2800	a	a	a	a	a	c	a	a	x	a
2800~2820	a	a	a	a	a	a	a	a	x	a
2820~2840	a	a	a	a	a	a	a	a	x	a
2840~2860	b	a	a	a	a	b	a	a	x	a
2860~2880	b	a	a	a	a	a	a	a	x	a
2880~2900	a	a	a	a	a	b	a	a	x	a
2900~2920	b	a	a	a	a	b	a	a	x	a
2920~2940	a	a	a	a	a	a	a	a	x	a
2940~2960	a	a	a	a	a	a	a	a	x	a
2960~2980	a	a	a	a	a	a	a	a	x	a
2980~3000	a	a	a	a	a	b	a	a	x	a
3000~3020	a	a	a	a	a	a	a	a	x	a
3020~3040	a	a	a	a	a	a	a	a	x	a
3040~3060	a	a	a	a	a	a	a	a	x	a
3060~3080	a	a	a	a	a	b	a	a	x	a
Station(m)	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	상태평가 결과
3080~3100	a	a	a	a	a	a	a	a	x	a
3100~3120	a	a	a	a	a	a	a	a	x	a
3120~3140	a	a	a	a	a	b	a	a	x	a
3140~3160	a	a	a	a	a	a	a	a	x	a
3160~3180	a	a	a	a	a	b	a	a	x	a
3180~3200	a	a	a	a	a	b	a	a	x	a
3200~3220	a	a	a	a	a	b	a	a	x	a
3220~3240	b	a	a	a	a	b	a	a	x	a
3240~3260	b	a	a	a	a	b	a	a	x	a
3260~3280	a	a	a	a	a	a	a	a	a	a
3280~3300	a	a	b	a	a	b	a	a	x	a
3300~3320	a	a	a	a	a	a	a	a	x	a
3320~3340	a	a	a	a	a	a	a	a	x	a
3340~3360	c	a	a	a	a	b	a	a	x	b

3360~3380	b	a	a	a	a	b	a	a	x	a
3380~3400	b	a	a	a	a	a	a	a	x	a
3400~3420	b	a	a	a	a	b	a	a	x	a
3420~3440	b	a	a	a	a	b	a	a	x	a
3440~3460	b	a	a	a	a	a	a	a	x	a
3460~3480	a	a	a	a	a	a	a	a	x	a
3480~3500	a	a	a	a	a	a	a	a	x	a
3500~3520	a	a	a	a	a	a	a	a	x	a
3520~3540	b	a	a	a	a	a	a	a	x	a
3540~3560	b	a	a	a	a	a	a	a	x	a
3560~3580	b	a	a	a	a	a	a	a	x	a
3580~3600	a	a	a	a	a	b	a	a	x	a
3600~3620	b	a	a	a	a	a	a	a	x	a
3620~3640	b	a	a	a	a	b	a	a	x	a
3640~3660	b	a	a	a	a	a	a	a	x	a
3660~3680	b	a	a	a	a	c	a	a	x	b
3680~3700	c	a	a	a	a	a	a	a	x	b
3700~3720	c	a	a	a	a	c	a	a	x	b
3720~3740	c	a	a	a	a	b	a	a	x	b
3740~3760	b	a	a	a	a	b	a	a	x	a
3760~3780	c	a	a	a	a	c	a	a	x	b
3780~3800	b	a	a	a	a	c	a	a	x	b
3800~3820	b	a	a	a	a	a	a	a	x	a
3820~3840	b	a	a	a	a	a	a	a	x	a
3840~3860	b	a	a	a	a	a	a	a	x	a
3860~3880	b	a	a	a	a	a	a	a	x	a
3880~3900	b	a	a	a	a	a	a	a	x	a
3900~3920	b	a	a	a	a	c	a	a	x	a
3920~3940	b	a	a	a	a	a	a	a	x	a
3940~3960	b	a	a	a	a	a	a	a	x	a
3960~3980	b	a	a	a	a	a	a	a	x	a
3980~4000	b	a	a	a	a	a	a	a	x	a
4000~4020	b	a	a	a	a	a	a	a	x	a
4020~4040	c	a	a	a	a	a	a	a	x	b
4040~4060	a	a	a	a	a	a	a	a	x	a
4060~4080	a	a	a	a	a	a	a	a	x	a
4080~4100	b	a	a	a	a	a	a	a	x	a
4100~4120	b	a	a	a	a	a	a	a	x	a
4120~4140	c	a	a	a	a	a	a	a	x	b
4140~4160	a	a	a	a	a	a	a	a	x	a
Station(m)	구역	누수	파손 및 손	바리	충분리 및	배터	재료	철근	타사하	상태평가

Station(m)	균열	누수	파손상	박리	박락	백태	분리	노출	탄산화	결과
4160~4180	a	a	a	a	a	a	a	a	x	a
4180~4200	a	a	a	a	a	a	a	a	a	a
평 균	b	a	a	a	a	a	a	a	a	a

항목	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	합계
결함 점수	3.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	3.1

결함지수	0.091
상태평가 결과	a