

가
우
의
치

아름다운 세상과
바스락거리는

KEY PLAN

△
나
하
오
오

하
전
만
후
7

바다면	자출면	천정면	아랫면
		①	
			②

손상 물량 집계 표								
NO		손상 내용		손상 현황				
	종류	폭 (m,mm)	길이 (m)	깊이 (m)	개소 (EA)	물량	단위	결합 상태
1	철근노출	0.25	1.0		2.0	0.5	m ²	c
2	파손	0.2	0.2		3.0	0.12	m ²	b
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								

발주처	 화성시청	문서	주식회사 성 본	문영	2019년 하반기 지방하천 배수문 정밀점검 용역	도면명												암거 박스 외관조사망도		도면번호		2019. 11. 19 ~ 2020. 01. 26	42																								
						축척												NONE SCALE		점검기간																											
번	레		문상관열		시공이음본리		백		테		철근부식		신축이음본체		세		굴		배수구		R		C		0.2	열		재료본리		박리, 파손		누수		철근노출		접촉식형		전류수		니토		도막탈락		표면부식		누수	