





6. 보강토옹벽(6공구)




정면도 (VIEW "A")




단면 A-A




단면 B-B



단면 C-C



단면 D-D



단면 E-E

(주)워드이앤오

Project Title

2016년 상반기 시설물 정기점검 용역

Drawing Title

보강토조립식옹벽(6공구) 정면도 및 단면도

Note

ID:6공구 보강토 조립식 옹벽(1)

보수이력

	기 준 규 역
	신 규 규 역
	보수부위재규역
	보 수(기보수)
	보 수(08. 하반기)
	보 수(09. 상반기)
	보 수(09. 하반기)
	보 수(10. 상반기)
	보 수(10. 하반기)
	보 수(11. 상반기)
	보 수(11. 하반기)
	보 수(12. 상반기)
	보 수(12. 하반기)
	보 수(13. 상반기)
	보 수(13. 하반기)
	보 수(14. 상반기)
	보 수(14. 하반기)
	보 수(15. 상반기)
	보 수(15. 하반기)


손상 현황 표

[illegible]


주) 손상의 폭과 길이는 m 이며, 단 균열의 폭은 mm 임

대구 ←


➡ 부산



KEY PLAN





SECTION



용역명	2016년 상반기 시설물 정기점검 용역
과업기간	2016. 04. 18 ~ 2016. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	001


10:6공구 보강토 조립식 옹벽(2)




손상 현황 표

[illegible]

KEY PLAN













SECTION




용역명	2016년 상반기 시설물 정기점검 용역
과업기간	2016. 04. 18 ~ 2016. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	002

10:6공구 보강토 조립식 옹벽(3)

보수 이력	
	기 준 규 역
	신 규 규 역
	보수부위재검열
 	보 수 (기보수)
 	보 수 (08. 하반기)
 	보 수 (09. 상반기)
 	보 수 (09. 하반기)
 	보 수 (10. 상반기)
 	보 수 (10. 하반기)
 	보 수 (11. 상반기)
 	보 수 (11. 하반기)
 	보 수 (12. 상반기)
 	보 수 (12. 하반기)
 	보 수 (13. 상반기)
 	보 수 (13. 하반기)
 	보 수 (14. 상반기)
 	보 수 (14. 하반기)
 	보 수 (15. 상반기)
 	보 수 (15. 하반기)

대 구 ←


➡ 부산




손상 현황 표

[illegible]

KEY PLAN




SECTION



용역명	2016년 상반기 시설물 정기점검 용역
과업기간	2016. 04. 18 ~ 2016. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	003

10:6공구 보강토 조립식 옹벽(4)

대 구 ←



KEY PLAN

The key plan shows the stadium's location within its urban context. The stadium bowl is centrally located, with concourses and seating areas indicated by hatching. Surrounding streets include 10th Avenue to the north, 11th Avenue to the south, and 12th Avenue to the east. The plan also shows the intersection of 10th and 11th Avenues, and the intersection of 11th and 12th Avenues. The stadium is situated between 10th and 11th Avenues, and between 11th and 12th Avenues.

SECTION

50. 10. 1000 C.T.C.

50. 10. 1000 C.T.C.

50. 10. 1000 C.T.C.

50. 10. 1000 C.T.C.

100. 10. 1000 C.T.C.

보수 이력	
	기 존 규 월
	신 규 규 월
	보수부위재균열
	보 수(기보수)
	보 수(08. 하반기)
	보 수(09. 상반기)
	보 수(09. 하반기)
	보 수(10. 상반기)
	보 수(10. 하반기)
	보 수(11. 상반기)
	보 수(11. 하반기)
	보 수(12. 상반기)
	보 수(12. 하반기)
	보 수(13. 상반기)
	보 수(13. 하반기)
	보 수(14. 상반기)
	보 수(14. 하반기)
	보 수(15. 상반기)
	보 수(15. 하반기)

[illegible]

용역명	2016년 상반기 시설물 정기점검 용역
-----	-----------------------

과업기간	2016. 04. 18 ~ 2016. 06. 30
------	-----------------------------

발 주 처	 신대구부산고속도로주식회사
-------	---

용역사	(주)위드이앤오
-----	----------

도면번호	004
------	-----