



[illegible][illegible]

[illegible][illegible]

여의도 공동구 - 의사당로 A 통신구 (STA. 0+040m ~ 0+060m)



손상물량표

[illegible]

서울시 시설관리공단



TITLE OF PROJECT

2019년 공동구 정밀점검용역 (여의도공동구)

TITLE OF SHIFT

의사당로 A 통신구 외관조사망도

여의도 공동구 - 의사당로 A 통신구 (STA. 0+060m ~ 0+080m)


[illegible]

서울시 시설관리공단

TITLE OF PROJECT

2019년 공동구 정밀점검용역 (여의도공동구)

TITLE OF SHIFT
의사당로 A 통신구 외관조사망도 ^{NONE}



SECTION	

[illegible]

	'14 보수완료	
		
		
	'12 보수완료	

	'12 보수완료	
		

		'14 보수완료
--	--	----------

	'12 보수완료	
---	----------	--

12 보수원료

'14 보수완료

 '12 보수완료

우박

환기구 외관조사망도


[illegible][illegible]

TITLE OF SHIFT
의사당로 A 통신구 외관조사망도

여의도 공동구 의사당로A 작업구 2번 (의사당로 A 120m)

KEYPLAN

SECTION



손상물량표

[illegible]

서울시 시설관리공단

TITLE OF PROJECT


2019년 공동구 정밀점검용역 (여의도공동구)

TITLE OF SHIFT

작업구 외관조사망도

The image displays three architectural drawings of the National Assembly building. On the left is a detailed floor plan of the main assembly hall, showing the seating arrangement and various service areas. In the center is a key plan showing the building's layout with labels for different sections. On the right is a cross-section of the building, showing the internal structure and the location of the assembly hall. The drawings are labeled in Korean: '국회의사당' (National Assembly Building), 'KEYPLAN', and 'SECTION'.

[illegible]

[illegible]


SECTION	

우벽


--

[illegible]

작업구 외관조사망도

[illegible]

TITLE OF SHIFT
의사당로 A 통신구 외관조사망도



SECTION

전력구

통신구

BOX A

BOX B

슬래브

12 모수완료

좌벽

11 모수완료

바닥


13

체수

A=1.2m x 1.2m

우벽


[illegible]

[illegible]

SECTION


전력구

통신구



[illegible]

우표

환기구 외관조사망도



여의도 공동구 - 의사당로 A 통신구 (STA. 0+260m ~ 0+280m)



손상률량표

연번	계측년도	구분	구분내용	손상률량					손상률		비고
				구분	구분	구분	구분	구분	손상률	손상률	
1	2007	구분	구분	0.1	1.20	1.20	m	1		-	
2	2015	구분	구분	0.2	1.00	1.00	m	1		-	
3	2017	구분(연차장모)	구분	2.0	8.00	18.00	m	1		-	
4	2019	구분	구분	0.1	0.20	0.02	m	1		-	신규

서울시 시설관리공단

TITLE OF PROJECT

2019년 공동구 정밀점검용역 (여의도공동구)

TITLE OF SHIFT

의사당로 A 통신구 외관조사망도

여의도 공동구 의사당로A 작업구 4번 (의사당로 A 268m)

KEYPLAN

SECTION

전면

좌벽

우표

배면

바다

손상물량표

[illegible]


서울시 시설관리공단

TITLE OF PROJECT

2019년 공동구 정밀점검용역 (여의도공동구)

TITLE OF SHIFT

작업구 외관조사망도



The architectural drawings include a detailed floor plan of the National Assembly building, a key plan, and a section view. The floor plan shows the layout of the building with various rooms and corridors. The key plan provides a simplified overview of the building's footprint. The section view shows a cross-section of the building, highlighting the structural elements and the internal space.

통 신 구	좌벽												
	슬래브												
	우벽												
	바닥												
		STA.0+300	302	304	306	308	310	312	314	316	318	STA.0+320	

손상물량표

[illegible]

KEYPLAN

SECTION	

[illegible]

슬래브	 ① '16 보수완료
좌벽	
바닥	
우벽	

			
배면	좌면	우면	

바탕

환기구 외관조사망도

