

공촌1교(하)

바닥판하면 손상현황

	
궁촌1교 하행선 바닥판하면 S1 재료분리 0.4*0.4	궁촌1교 하행선 바닥판하면 S1 파손 0.3*0.8
	
궁촌1교 하행선 바닥판하면 S1 파손 0.4*0.2	궁촌1교 하행선 바닥판하면 S1 파손 0.4*0.2

거더 및 가로보 손상현황



궁촌1교 하행선 거더 S1-G1 인양홀 박락 0.1*0.2



궁촌1교 하행선 거더 S1-G2 인양홀 박락 0.1*0.2



궁촌1교 하행선 거더 S1-G3 인양홀 박락 0.1*0.2



궁촌1교 하행선 거더 S1-G3 인양홀 박락 0.3*0.3



궁촌1교 하행선 거더 S1-G4 인양홀 박락 0.3*0.3



궁촌1교 하행선 거더 S1-G5 인양홀 박락 0.3*0.3

교대, 교각 손상현황



궁촌1교 하행선 교각 P1 균열 0.2/1.0 -신규-



궁촌1교 하행선 교각 P1 균열 0.2/3.0 -신규-



궁촌1교 하행선 교각 P1 균열 0.2/3.0 -신규-



궁촌1교 하행선 교각 P1 망상균열 0.2*0.5*1.0
-신규-



궁촌1교 하행선 교각 P1 망상균열 0.2*1.0*0.5
-신규



궁촌1교 하행선 교각 P1 망상균열 0.2*1.0*0.5
-신규-

교대, 교각 손상현황



궁촌1교 하행선 교각 P1 표면오염 4.0*2.0
-신규-



궁촌1교 하행선 교대 A1 거푸집미제거 2EA
-신규-



궁촌1교 하행선 교대 A1 누수흔적 4.0*3.0
-신규-



궁촌1교 하행선 교대 A1 파손 1.0*2.0 -신규-



궁촌1교 하행선 교대 A1 파손 1.0*3.0 -신규-



궁촌1교 하행선 교대 A1 표면오염 0.5*0.7
-신규-