



### 3. 용벽





---

## 01. 패널식 옹벽 01

---



## 전경 및 작업사진




전면부 전경



배수로 전경



하부 전경



상부 성토부 전경



광파기를 이용한 측량 작업



경사계를 이용한 경사도 측정

지반, 기초부 손상현황 사진

|                                                                                    |        |                                                                                     |        |
|------------------------------------------------------------------------------------|--------|-------------------------------------------------------------------------------------|--------|
|   |        |   |        |
| 현황                                                                                 | • 상태양호 | 현황                                                                                  | • 상태양호 |
| 원인                                                                                 | • -    | 원인                                                                                  | • -    |
| 대책                                                                                 | • -    | 대책                                                                                  | • -    |
|  |        |  |        |
| 현황                                                                                 | • 상태양호 | 현황                                                                                  | • 상태양호 |
| 원인                                                                                 | • -    | 원인                                                                                  | • -    |
| 대책                                                                                 | • -    | 대책                                                                                  | • -    |

전면부 손상현황 사진

|                                                                                   |        |                                                                                    |        |
|-----------------------------------------------------------------------------------|--------|------------------------------------------------------------------------------------|--------|
|  |        |  |        |
| 현황                                                                                | • 상태양호 | 현황                                                                                 | • 상태양호 |
| 원인                                                                                | • -    | 원인                                                                                 | • -    |
| 대책                                                                                | • -    | 대책                                                                                 | • -    |

|                                                                                    |        |                                                                                     |        |
|------------------------------------------------------------------------------------|--------|-------------------------------------------------------------------------------------|--------|
|  |        |  |        |
| 현황                                                                                 | • 상태양호 | 현황                                                                                  | • 상태양호 |
| 원인                                                                                 | • -    | 원인                                                                                  | • -    |
| 대책                                                                                 | • -    | 대책                                                                                  | • -    |

## 주변영향인자 손상현황 사진

|                                                                                    |               |                                                                                     |               |
|------------------------------------------------------------------------------------|---------------|-------------------------------------------------------------------------------------|---------------|
|   |               |   |               |
| 현 황                                                                                | • 배수시설 상태현황   | 현 황                                                                                 | • 배수시설 상태현황   |
| 원 인                                                                                | • -           | 원 인                                                                                 | • -           |
| 대 책                                                                                | • -           | 대 책                                                                                 | • -           |
|  |               |  |               |
| 현 황                                                                                | • 상부 성토부 상태양호 | 현 황                                                                                 | • 상부 성토부 상태양호 |
| 원 인                                                                                | • -           | 원 인                                                                                 | • -           |
| 대 책                                                                                | • -           | 대 책                                                                                 | • -           |