






참 여 기 술 진

참여 구분	참여 분야	소 속	자 격	성 명	참여 기간	비고
책임 기술자	과업 총괄	(주)명성 엔지니어링	특급	이 상 훈	2026. 06. 22 ~2026. 06. 30	
참여 기술자	현장조사 보고서작성	“	특급	정 지 운	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	특급	장 진 원	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	특급	황 상 훈	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	특급	서 동 진	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	중급	손 기 영	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	초급	양 주 윤	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	초급	전 희 균	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	초급	이 석 진	2026. 06. 22 ~2026. 06. 30	
	현장조사 보고서작성	“	초급	이 석 진	2026. 06. 22 ~2026. 06. 30	


시설물 위치도(1/6)




시설물 위치도(2/6)




시설물 위치도(3/6)




시설물 위치도(4/6)



시설물 위치도 (5/6)



시설물 위치도(6/6)



시설물별 전경사진



원평1교



샘내IC1교



샘내IC2교



천천IC1교



쌍학터널



계단식옹벽 (STA.2+040~2+148)

