



KEY PLAN




불광천포장부 J53(1K 445) ~ J55(1K 490)

손상물량표

번	레	손상 위치	적출년도	결함규모						단위	개소	비고
				내 용	폭	길이	깊이	물량				
1		53-54	S	2013	망상균열	3.5	19.0		66.50	m	1	신규
2		54	S	2013	탄성조인트파손	0.8	10.0		10.00	m	1	신규
3		54-55	S	2013	포장파손	2.5	10.0		25.0	m	1	신규
4		55	S	2013	탄성조인트파손	0.8	10.0		10.00	m	1	신규
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
17												
18												
19												
20												
21												
22												
23												
24												
25												
26												
27												
28												
29												
30												
31												
32												
33												

-1순위 : Type-7~9 (예일여고~역말사거리)
-2순위 : Type-9~11 (역말사거리~신사오거리) 및 조인트 손상
-3순위 : Type-1~7 (시점~예일여고) 및 포장균열



범례



단위

/mm

T=mm

A=mm

지름

두께

면적

발주처

서울특별시 서부도로사업소

용역사

(주)한국시설안전연구원

PROJECT

불광천1복개 정밀안전진단 및 녹번천복개 정밀점검 용역

TITLE

불광천포장부 J53(1K 445) ~ J55(1K 490)

SCALE

NOTE

0-13