



KEY PLAN




불광천포장부 J95(2K 489) ~ J96(2K 498)

손상물량표

범례		① ~ 2013 신규		기① - 기존손상		① 보수완료					
번 호	손 상 위 치		적출년도	결함규모						비 고	
				내 용	폭	길이	깊이	물 량	단위		개소
1	95-96	S	2013	망상균열	3.5	9.0		31.50	m	1	신규
2											
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											
16											
17											
18											
19											
20											
21											
22											
23											
24											
25											
26											
27											
28											
29											
30											
31											
32											
33											

-1순위 : Type-7~9 (예일여고~역달사거리)
 -2순위 : Type-9~11 (역달사거리~신사오거리) 및 조인트 손상
 -3순위 : Type-1~7 (시점~예일여고) 및 포장균열



범례



단위



발주처

서울특별시 서부도로사업소

용역사

(주)한국시설안전연구원

PROJECT

불광천1복개 정밀안전진단 및 녹번천복개 정밀점검 용역

TITLE

불광천포장부
J95(2K 489) ~ J96(2K 498)

SCALE

NONE

0-23