




(구)남한강교 외관조사망도 바닥판 주형 S6



손상량표

번호	손상 내용	손상 규모			단위	비고
		폭	길이	수량	수량	
1	재문판리	0.3	0.5	1	0.15	m ²
2	파손	0.2	1.0	1	0.20	m ²
3	철근노출	0.1	0.1	2	0.02	m ²
4	박락	0.1	0.1	1	0.01	m ²
5	철근노출	0.1	0.1	3	0.03	m ²
6	균열(Cw=0.3mm 이하)		0.2	2	0.40	m
7	철근부식			16	16.00	ea
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						



서늘