




(구)남한강교 외관조사망도 바닥판 주형 S7



손상량표

번호	손상 내용	손상 규모			단위	비고
		폭	길이	수량	물량	
1	철근노출	0.1	0.1	1	0.01	m ²
2	처음노출	0.3	0.3	1	0.09	m ²
3	철근노출	0.1	0.1	1	0.01	m ²
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						



시