



(구)남한강교 외관조사망도 교각 P4

KEY PLAN




SECTION




손상 물량 표

A2축	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27
A1축	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27

< 서울 방향 >



< 원주 방향 >



영역명	(구)남한강교 정밀안전진단 영역	발주처	경기도여주시	용역사	케이티알기술(주)	도면명	교각 P4	도면	79
-----	-------------------	-----	--------	-----	-----------	-----	-------	----	----