



오 계 교

교대 손상현황도

ABUT 1, 2




- ABUT 1 -



① 0.2/3.0x10ea

- ABUT 2 -



③ 0.3/3.0x2ea

⑤ 0.2/3.0