


장 항 교


바닥판 상면 손상현황도

A1 ~ A2(S1)

KEY PLAN



범 례			
콘 열	철근노출	강재부식	백 데
누 수	파 손	박 락	열 화
재료분리	토사퇴적	들 음	미세망상




주록리



① 토사퇴적
0.5x15.0x2ea

1/7 2/7 3/7 4/7 5/7 6/7

A2



후 리