


천 서 2 교

바닥판 상면 손상현황도

A1 ~ P1(S1)



KEY PLAN

← 천서리



→ 송촌리

범례




송촌리



② 연석열화
0.5x8.0x2ea

① 파손
5.0x8.0

③ 토사퇴적
0.5x8.0



천서리