


천 서 2 교

바닥판 상면 손상현황도

P2 ~ A2(S3)



KEY PLAN

천서리 ←



→ 송촌리

범례




송촌리



② 연석열화
0.5x8.0x2ea

① 파손
5.0x8.0



천서리