



운 촌 1 교

바닥판 하면 손상현황도

$$A1 \sim P1(S1)$$

## KEY PLAN



→ 여 주

## 범례



50



철근노출



강재부식



백 태


$$\begin{array}{cc} \text{ㄴ} & \text{수} \\ \text{ㅌ} & \text{ㅍ} \end{array}$$


파 손



한글



화재



## 자료분리




토사퇴적



|     |     |
|-----|-----|
| U/N | 3/D |
|-----|-----|



미세망상



여 주



Figure 1: Plan view of the test section. The diagram shows a rectangular test section with a grid of dashed lines. The horizontal axis is labeled with fractions from 1/8 to 7/8, and the vertical axis is labeled with fractions from 0 to 6/6. A central area is labeled "① 균열부 백태 0.2/0.5x3ea". A downward arrow at the bottom is labeled "이 천".