


소 양 천 교

바닥판 상면 손상현황도

P2 ~ A2(S3)

KEY PLAN

가업동 ←



→ 홍문동

범례



콘크리트



철근노출



강재부식



박탈



균열



누수



파손



박락



재료분리




토사퇴적



들뜸



미세망상



홍문동



② 연석 파손
0.4x0.5

A2

1/7

2/7

3/7

4/7

5/7

6/7

① L±19.0

6/6

5/6

4/6

3/6

2/6

1/6

0

P2

1 2

3

4 5



가업동