


가 업 교


바닥판 상면 손상현황도

A1 ~ A2(S1)

KEY PLAN



범례



월설동

① 후타재 균열
0.1/0.2x10ea



1/11 2/11 3/11 4/11 5/11 6/11 7/11 8/11 9/11 10/11

A2

6/6

5/6

4/6

3/6

2/6

1/6

0

④ 배수구 막힘, 덮개망실
14ea

③ 열화
1.0x3.0

A1

① ②



② 후타재 균열
0.1/0.2x10ea

점봉동