


결 은 교

바닥판 상면 손상현황도

P1 ~ A2(S2)



KEY PLAN

이 천 ←



→ 여 주

범 례



여 주



① 유간부 토사퇴적
L=10.0

② 후타재 균열
0.1/0.2x10ea



③ 0.3/0.7x5ea

6/6

5/6

④ 0.3/0.7x5ea

4/6

3/6

2/6

1/6

0

③ 0.3/0.7x5ea

① ②

③

④ ⑤



이 천