


당 우 교

바닥판 상면 손상현황도

P5 ~ A2(S6)

KEY PLAN


← 당산리



→ 가산리

범례

|      |      |      |      |
|------|------|------|------|
|      |      |      |      |
| 균열   | 철근노출 | 강재부식 | 백태   |
|      |      |      |      |
| 누수   | 파손   | 박락   | 열화   |
|      |      |      |      |
| 재료분리 | 토사퇴적 | 돌출   | 미세망상 |




가산리

③ 패임  
0.2x3.0



② 유간부 토사퇴적  
L=10.0



1/7 2/7 3/7 4/7 5/7 6/7

① 열화  
1.0x15.0x2ea

A2

① 열화  
1.0x15.0x2ea

A2

P5

1 2

3

4 5

6/6

5/6

4/6

3/6

2/6

1/6

0



당산리