


단 현 1 교


바닥판 상면 손상현황도

P3 ~ A2(S4)

KEY PLAN




범례			
	균열		철근노출
	강재부식		백태
	누수		파손
	박락		열화
	재료분리		토사퇴적
	돌출		미세망상



관한리



① 후타재 균열
0.1/0.2x20ea



A2

6/6

5/6

4/6


3/6

2/6

1/6

0

P3



② 후타재 균열
0.1/0.2x10ea



여주