


와 평 교

바닥판 상면 손상현황도


P1 ~ A2(S2)

KEY PLAN

← 간매리



→ 부평리




부평리



② 유간부 토사퇴적
L=10.0

③ 조인트 파손
L=1.0



Ⓐ2

1/7 2/7 3/7 4/7 5/7 6/7

6/6

5/6

4/6

3/6

2/6

1/6

0

Ⓐ1

① ②

③

④ ⑤

① L=12.0



간매리