


도 장 교

바닥판 상면 손상현황도



A1 ~ P1(S1)

KEY PLAN

여주 ←





범례



관한리

① 유간 토사퇴적
L=10.0

② 후타재 파손
1.0x1.5



③ 유간 토사퇴적
L=10.0

④ 후타재 파손
0.2x0.3

⑤ 후타재 파손
0.2x2.2

↓
여주