


도 장 교

바닥판 상면 손상현황도

P1 ~ P2(S2)


KEY PLAN

여주 ←



→ 관한리

범례




관한리



④ 후타재 파손
0.2x0.5

⑤ 덮개 파손
L=0.5



1/9

2/9

3/9

4/9

5/9


6/9

7/9

8/9

P2

6/6



5/6

4/6

3/6

2/6

1/6

0

P1

① ②

③

④ ⑤



여주