


도 장 교


바닥판 상면 손상현황도

P3 ~ A2(S4)

KEY PLAN



범 례			
균열	철근노출	강재부식	백태
누수	파손	박락	열화
재료분리	토사퇴적	돌움	미세망상




관한리



② 후타재 파손
1.0x4.0


③ 후타재 파손
1.0x1.0



1/9 2/9 3/9 4/9 5/9 6/9 7/9 8/9

A2

6/6



5/6

4/6

3/6

2/6

1/6

0

P3

1 2 3 4 5



여주