


현 암 3 교

바닥판 상면 손상현황도

P1 ~ A2(S2)



KEY PLAN

이 천 ←



→ 여 주

범례



여 주



② 유간부 토사되적
L=5.0

(A2)



6/6

① 배수구 막힘
2ea

5/6

4/6

3/6

2/6

1/6

0

(P1)

③ 0.2/0.6

① ②

③

④ ⑤



이 천