

[오송역(T1)] [Rahmen교 구간] 결과표

개별교량명 오송역(T1)													
부재의 분류		상부구조		2차부재	기타부재				받침	하부구조		내구성 요소	
번호	구조형식	바닥판	거더	가로보	궤도부	배수시설	난간, 연석, 보도부	신축이음	교량받침	하부	기초	탄산화(상)	탄산화(하)
S1	Rahmen	a	b	a	N/A	a	b	a	a	a	Q	N/A	N/A
S1-1	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S2	Rahmen	a	a	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S2-1	Rahmen	a	b	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S3	Rahmen	a	a	a	N/A	a	b	N/A	N/A	a	Q	N/A	N/A
S3-1	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S4	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S4-1	Rahmen	a	a	a	N/A	a	a	a	a	b	Q	N/A	N/A
S5	Rahmen	a	a	a	N/A	a	b	a	a	b	Q	N/A	N/A
S5-1	Rahmen	c	a	a	N/A	a	a	a	a	b	Q	N/A	N/A
S6	Rahmen	a	b	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S6-1	Rahmen	b	a	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S7	Rahmen	a	a	a	N/A	a	b	N/A	N/A	b	Q	N/A	N/A
S7-1	Rahmen	a	a	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S8	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S8-1	Rahmen	a	a	a	N/A	a	a	a	a	b	Q	N/A	N/A
S9	Rahmen	a	a	a	N/A	a	b	a	a	a	Q	N/A	N/A
S9-1	Rahmen	c	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S10	Rahmen	b	b	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S10-1	Rahmen	b	b	b	N/A	a	c	N/A	N/A	a	Q	N/A	N/A
S11	Rahmen	a	a	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S11-1	Rahmen	a	a	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S12	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S12-1	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S13	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S13-1	Rahmen	a	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S25	Rahmen	b	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S25-1	Rahmen	b	a	a	N/A	a	a	a	a	a	Q	N/A	N/A
S26	Rahmen	b	a	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S26-1	Rahmen	a	a	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S27	Rahmen	a	a	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S27-1	Rahmen	a	a	a	N/A	a	a	N/A	N/A	c	Q	N/A	N/A
S28	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S28-1	Rahmen	a	b	a	N/A	a	a	a	a	a	Q	N/A	N/A
S29	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S29-1	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S30	Rahmen	a	b	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S30-1	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S31	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S31-1	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S32	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S32-1	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S33	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S33-1	Rahmen	a	b	a	N/A	a	a	a	a	b	Q	N/A	N/A
S34	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S34-1	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S35	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S35-1	Rahmen	a	b	a	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
C36	Rahmen	N/A	N/A	N/A	N/A	N/A	N/A	a	a	b	Q	N/A	N/A
C36-1	Rahmen	N/A	N/A	N/A	N/A	N/A	N/A	a	a	b	Q	N/A	N/A
평균		0.125	0.146	0.106	N/A	0.100	0.117	0.100	0.100	0.158	N/A	N/A	N/A
가중치		27	21	5	N/A	3	2	3	3	29	N/A	N/A	N/A
(평균X가중치)/가중치합		0.034	0.031	0.005	N/A	0.003	0.002	0.003	0.003	0.046	N/A	N/A	N/A
1. 환산결함도 점수 =												0.127	
2. 상태평가 결과 =												a	

[오송역 Rahmen구간] 결과표

개별 교량명 :		오송역(T1)				
구분	구조형식	환산 결함도점수	상태평가 결과	연장(m)	연장비	환산결함도점수 X 연장비
본 교	Rahmen교	0.127	a	558	1.000	0.127
합계(Σ)				558	1.000	0.127
<평가자 의견>						
1. 환산결함도 점수 =						0.127
2. 상태평가 결과 =						a

[오송역(T1)] 결과표

교 량 명 : 오송역(T1)						
종류	구분	환산 결함도점수	상태평가 등급	연장 (M)	연장비	환산결함도점수 X 연장비
Rahmen 교량	본교	0.127	a	558	1.000	0.127
합계(Σ)				558	1.000	0.127
<평가자 의견>						
1. 평가지수 =						0.127
2. 상태평가 결과 =						A