




88. 황등제 2교 토공노반(G44)

											
위치	STA. 83K309-319	선별	T1	위치	TCL	위치	STA. 83K413-423	선별	T2	위치	TCL
내용	박락	A= 0.1x0.1				내용	파손	A= 0.2x0.2			
											
위치	STA. 83K413-423	선별	T1	부위	HSB	위치	STA. 83K673-683	선별	T2	부위	TCL
내용	균열	Cw= 0.6/1.4				내용	균열	Cw= 0.1/0.4			
											
위치	STA. 83K704-714	선별	T1	부위	TCL	위치	STA. 83K860-870	선별	T1	부위	HSB
내용	균열	Cw= 0.1/0.4				내용	박락	A= 0.1x0.1			

											
위치	STA. 83K735-745	선별	T2	부위	TCL	위치	STA. 83K735-745	선별	T2	부위	TCL
내용	균열보수부					내용	균열보수부				