








18. 유정교 토공노반(G55)

																							
위치	STA. 115K540-550				선별	T1		위치	TCL				위치	STA. 115K600-610				선별	T1		위치	TCL	
내용	박락				A= 0.2x0.3				내용	균열				Cw= 0.6/0.5									
																							
위치	STA. 115K910-920				선별	T1		위치	HSB				위치	STA. 115K910-920				선별	T1		위치	TLC	
내용	파손				A= 0.2x0.3				내용	박리				A= 0.1x0.2									
																							
위치	STA. 115K910-920				선별	T2		위치	TCL				위치	STA. 116K910-920				선별			위치	채움	
내용	파손				A= 0.1x0.1				내용	균열				Cw= 0.5/1.6									

							
위치	STA. 116K910-920	선별		위치	STA. 116K930-940	선별	
내용	균열	Cw= 0.5/0.8		내용	균열	Cw= 0.5/1.6	