




2. 만경강교 토공노반(G47)

											
위치	STA. 93K794-804	선별	T1	위치	HSB	위치	STA. 93K846-856	선별	T1	위치	TCL
내용	박락	A= 0.2x0.3				내용	균열	Cw= 0.3/0.3			
											
위치	STA. 93K919-929	선별	T1	부위	HSB	위치	STA. 93K919-929	선별	T2	부위	TCL
내용	균열	Cw= 0.5/0.4				내용	균열	Cw= 0.3/0.4			
											
위치	STA. 93K950-960	선별	T2	부위	TCL	위치	STA. 93K950-960	선별	T2	부위	침목
내용	균열	Cw= 0.3/0.4				내용	균열	Cw= 0.3/0.2			

													
위치	STA. 94K300-210		선별	T1	위치	TCL	위치	STA. 94K300-210		선별	T1	위치	HSB
내용	균열		Cw= 0.3/1.0				내용	균열		Cw= 0.2/0.55			
													
위치	STA. 94K293-304		선별	T2	부위	HSB							
내용	박락		A= 0.1x0.1										