

20. 연정교 토공노반(G56)



위치	STA. 120K850-860	선별	T2	위치	침목
내용	경계부 균열	Cw= 0.2/2.3			




위치	STA. 121K000-010	선별		위치	채움
내용	균열	Cw= 0.3/1.6			




위치	STA. 121K000-010	선별	T1	위치	TCL
내용	균열	Cw= 0.2/0.5			





위치	STA. 121K300-310	선별	T2	위치	TCL
내용	파손	A= 0.1x0.3			



위치	STA. 121K300-310	선별	T2	위치	TCL
내용	파손	A= 0.1x0.5			



위치	STA. 121K510-517	선별	T2	위치	TCL
내용	균열	Cw= 0.3/0.1			

									
위치	STA. 121K510-517	선별	T2	위치	TCL				
내용	균열	Cw= 0.3/0.2							