




30. 한교천교 토공노반(G61)




위치	STA. 127K550-560	선별	T1	위치	TCL
내용	균열	Cw=	0.5/0.1		




위치	STA. 127K580-590	선별	T1	위치	TCL
내용	균열	Cw=	0.5/0.5		




위치	STA. 127K640-650	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.5		







위치	STA. 127K670-680	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.5		



위치	STA. 127K680-690	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.4		



위치	STA. 127K680-690	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.4		

																									
위치	STA. 127K690-700				선별	T1		위치	TCL				위치	STA. 127K730-740				선별	T2		위치	TCL			
내용	균열				Cw= 0.3/0.5								내용	균열				Cw= 0.3/0.4							
																									
위치	STA. 127K730-740				선별	T2		위치	TCL				위치	STA. 127K730-740				선별	T2		위치	TCL			
내용	균열				Cw= 0.3/0.4								내용	균열(2EA)				Cw= 0.3/0.4							
																									
위치	STA. 127K750-760				선별	T1		위치	HSB				위치	STA. 127K770-780				선별	T1		위치	TCL			
내용	파손				A= 0.4x0.4								내용	망상균열				A= 0.4x1.0							