



31. 남산교 (B44)




위치	1 SPAN -2	선별	T1	부위	TCL
내용	균열	Cw= 0.1/0.4			




위치	5 SPAN -2	선별	T1	부위	TCL
내용	균열	Cw= 0.1/0.4			



위치	5 SPAN -5	선별	T1	부위	TCL
내용	균열	Cw= 0.1/0.4			



위치	7 SPAN -1	선별	T1	부위	TCL
내용	균열	A= 0.2/0.4			



위치	1 SPAN -4	선별	T2	부위	TCL
내용	균열	Cw= 0.1/0.4			




위치	5 SPAN -2	선별	T2	부위	TCL
내용	균열	Cw= 0.1/0.4			



위치	5 SPAN -4	선별	T2	부위	TCL	위치	3 SPAN -4	선별	T1	부위	TCL
내용	망상균열	A= 0.2X7.0				내용	망상균열	A= 0.3X7.0			



위치	3 SPAN -5	선별	T2	부위	TCL	위치	3 SPAN -6	선별	T1	부위	TCL
내용	재료분리	A= 0.1X0.1				내용	재료분리	A= 0.3X0.8			



위치	4 SPAN -2	선별		부위		위치		선별		부위	
내용	파손	A=				내용					