



30. 남산교 토공노반(G62)

											
위치	STA. 128K260-270	선별	T2	위치	TCL	위치	STA. 128K270-280	선별		위치	채움
내용	균열		Cw= 0.3/0.5			내용	균열		Cw= 0.3/1.6		
											
위치	STA. 128K330-340	선별	T1	위치	TCL	위치	STA. 128K350-360	선별	T1	위치	TCL
내용	망상균열		A= 0.4x0.4			내용	시공불량(2EA)		A= 0.4x0.5		
											
위치	STA. 128K490-500	선별	T1	위치	TCL	위치	STA. 128K560-570	선별	T1	위치	TCL
내용	파손		A= 0.1x0.2			내용	망상균열		A= 0.5x1.0		



위치	STA. 128K560-570	선별	T1	위치	TCL
내용	균열	Cw= 0.3/0.4			



위치	STA. 128K570-580	선별	T2	위치	TCL
내용	망상균열	A= 0.4x0.4			



위치	STA. 128K580-590	선별	T2	위치	TCL
내용	재료분리	A= 0.3x2.0			



위치	STA. 128K600-610	선별	T2	위치	TCL
내용	재료분리	A= 0.2x1.5			