


## 34. 정읍고가 토공노반(G63)

---





|    |                  |             |    |    |
|----|------------------|-------------|----|----|
| 위치 | STA. 129K560-570 | 선별          | 위치 | 채움 |
| 내용 | 균열               | Cw= 0.3/1.6 |    |    |



|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 129K690-700 | 선별          | T1 | 위치 | HSB |
| 내용 | 균열               | Cw= 0.3/0.7 |    |    |     |




|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 129K890-900 | 선별          | T1 | 위치 | TCL |
| 내용 | 망상균열             | A= 2.5x10.0 |    |    |     |



|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 129K960-970 | 선별          | T2 | 위치 | TCL |
| 내용 | 균열               | Cw= 0.3/0.7 |    |    |     |



|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 130K090-100 | 선별          | T2 | 위치 | HSB |
| 내용 | 균열               | Cw= 0.4/0.7 |    |    |     |



|    |                  |            |    |    |     |
|----|------------------|------------|----|----|-----|
| 위치 | STA. 130K210-220 | 선별         | T2 | 위치 | HSB |
| 내용 | 파손               | A= 0.4x1.5 |    |    |     |