




36. 읍지천교 토공노반(G64)

																							
위치	STA. 130K260-270				선별	T2	위치	TCL				위치	STA. 130K410-420				선별	T2	위치	TCL			
내용		파손				A= 0.2x0.1				내용		재료분리				A= 0.2x0.1							
																							
위치	STA. 130K560-570				선별	T2	위치	침목				위치	STA. 130K590-600				선별	T1	위치	침목			
내용		경계부 균열				Cw= 0.2/2.3				내용		경계부 균열				Cw= 0.2/2.3							
																							
위치	STA. 130K630-640				선별	T1	위치	TCL				위치	STA. 130K730-740				선별	T2	위치	침목			
내용		박락				A= 0.2x0.2				내용		파손				A= 0.1x0.1							



위치	STA. 130K730-740	선별	T2	위치	침목
내용	파손	A= 0.1x0.1			



위치	STA. 130K750-760	선별	T2	위치	
내용	침목도상분리	10			



위치	STA. 130K750-760	선별	T2	위치	
내용	침목도상분리	11			



위치	STA. 130K778-788	선별	T2	위치	우
내용	침목도상분리	13			



위치	STA. 130K858-868	선별	T2	위치	HSB
내용	파손	A= 0.2x0.3			




위치	STA. 130K858-868	선별	T2	위치	HSB
내용	파손	A= 0.2x0.2			



위치	STA. 131K018-028	선별	T1	위치	HSB
내용	파손	A= 0.2x0.2			



위치	STA. 131K038-048	선별	T2	위치	
내용	침목도상분리	15			



위치	STA. 131K048-058	선별	T2	위치	TCL
내용	파손	A= 0.2x0.2			




위치	STA. 131K068-078	선별	T2	위치	
내용	침목도상분리(2EA)	8			




위치	STA. 131K088-98	선별	T1	위치	TCL
내용	파손	A= 0.1x0.1			



위치	STA. 131K088-98	선별	T2	위치	
내용	침목도상분리	2			

											
위치	STA. 131K428-438	선별	T1	위치	HSB	위치	STA. 131K428-438	선별	T2	위치	TCL
내용	백태		A= 0.3x0.2			내용	백태		A= 0.3x0.2		
											
위치	STA. 131K438-448	선별	T2	위치	TCL	위치	STA. 131K448-458	선별		위치	채움
내용	백태		A= 0.2x5.0			내용	균열		Cw= 0.5/3.2		
											
위치	STA. 131K458-468	선별	T1	위치	HSB	위치	131K458-468	선별	T2	위치	HSB
내용	백태		A= 0.2x1.0			내용	균열		Cw= 0.5/0.6		




위치	131K518-528	선별	T1	위치	HSB
내용	균열	Cw= 0.5/1.0			




위치	131K618-628	선별	T2	위치	HSB
내용	균열	Cw= 0.5/0.6			



위치	132K351-361	선별	T2	위치	
내용	침목도상분리	4			



위치	131K898-908	선별	T2	위치	HSB
내용	균열	Cw= 0.5/0.6			



위치	131K898-908	선별		위치	채움
내용	균열	Cw= 0.5/2.3			



위치	131K978-988	선별		위치	채움
내용	균열	Cw= 0.5/1.8			



위치	선별	위치				
내용						