




6. 부용1고가 토공노반(G49)



위치	STA. 101K845-855	선별	T2	위치	TCL
내용	균열		Cw= 0.5/0.2		



위치	STA. 101K845-855	선별	T2	위치	TCL
내용	균열		Cw= 0.5/0.1		



위치	STA. 101K855-865	선별	T2	위치	TCL
내용	균열		Cw= 0.5/0.1		



위치	STA. 101K855-865	선별	T2	위치	침목
내용	경계부 균열		Cw= 0.5/2.2		




위치	STA. 101K855-865	선별	T2	위치	TCL
내용	침목도상분리				




위치	STA. 101K865-867	선별	T1	위치	HSB
내용	재료분리		A= 0.3x0.5		



위치	STA. 101K907-917	선별	T2	위치	HSB
내용	균열		Cw= 0.5/0.8		



위치	STA. 101K938-949	선별	T2	위치	TCL
내용	균열		Cw= 0.5/0.2		



위치	STA. 101K949-959	선별	T2	위치	TCL
내용	균열		Cw= 0.5/0.2		




위치	STA. 102K064-075	선별	T1	위치	TCL
내용	망상균열		A= 1.5x0.4		



위치	STA. 102K086-097	선별	T1	위치	HSB
내용	균열		Cw= 1.0/0.6		



위치	STA. 102K086-097	선별	T2	위치	HSB
내용	균열		Cw = 1.0x0.4		

									
위치	STA. 102K097-102	선별	T1	위치	TCL	위치		선별	위치
내용	실링재열화	L= 0.8				내용			