

14. 달성터널 토공노반(G73)



위치	Sta. 150k653-665	선별	T2	위치	채움
내용	균열	Cw= 0.3/2.0			



위치	Sta. 150k705-715	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	Sta. 150k705-715	선별	T2	위치	TCL
내용	침목도상분리	1EA			






위치	Sta. 150k705-715	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	Sta. 150k705-715	선별	T1	위치	HSB
내용	균열	Cw= 0.4/0.6			



위치	Sta. 150k705-715	선별	T2	위치	TCL
내용	침목도상분리	1EA			

																		
위치	Sta. 150k685-695	선별	T2	위치	TCL	위치	Sta. 150k665-675	선별	T1	위치	HSB							
내용	경계부 균열(보수)	Cw= 0.1/2.3				내용	균열	Cw= 1.0/1.5										
																		
위치	Sta. 150k653-665	선별	T2	위치								채움						
내용	파손	A= 0.2x0.2																
																		
위치		선별		위치		위치		선별		위치								
내용						내용												