



















17. 죽청터널 (U21)

											
위치	Sta. 152k393-403	선별	T1	위치	보조	위치	Sta. 152k373-383	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 152k373-383	선별	T1	위치	보조	위치	Sta. 152k353-363	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 152k343-353	선별	T1	위치	보조	위치	Sta. 152k343-353	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		

											
위치	Sta. 152k333-343	선별	T1	위치	보조	위치	Sta. 152k293-303	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 152k273-283	선별	T1	위치	보조	위치	Sta. 152k263-273	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 152k233-243	선별	T1	위치	보조	위치	Sta. 152k203-213	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		

											
위치	Sta. 151k993-152k003	선별	T1	위치	보조	위치	Sta. 151k883-893	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k823-833	선별	T1	위치	TCL	위치	Sta. 151k703-713	선별	T1	위치	보조
내용	파손(보수)		A= 0.1x0.1			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k683-693	선별	T1	위치	보조	위치	Sta. 151k633-643	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		

											
위치	Sta. 151k513-523	선별	T1	위치	보조	위치	Sta. 151k503-513	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k423-433	선별	T1	위치	보조	위치	Sta. 151k403-413	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/0.8		
											
위치	Sta. 151k383-393	선별	T1	위치	TCL	위치	Sta. 151k383-393	선별	T1	위치	TCL
내용	파손		A= 0.1/0.1			내용	균열(보수)		Cw= 0.6/0.4		




위치	Sta. 151k373-383	선별	T1	위치	보조
내용	균열	Cw= 0.5/1.0			




위치	Sta. 151k343-353	선별	T1	위치	보조
내용	균열	Cw= 0.5/0.8			




위치	Sta. 151k293-303	선별	T1	위치	TCL
내용	균열	Cw= 0.5/2.5			









위치	Sta. 151k293-303	선별	T1	위치	보조
내용	균열	Cw= 0.5/1.0			











위치	Sta. 151k253-263	선별	T1	위치	보조
내용	균열	Cw= 0.5/1.0			




위치	Sta. 151k513-523	선별	T1	위치	보조
내용	균열	Cw= 0.5/1.0			

											
위치	Sta. 151k223-233	선별	T1	위치	보조	위치	Sta. 151k203-213	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k203-213	선별	T1	위치	보조	위치	Sta. 151k163-173	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k153-163	선별	T1	위치	보조	위치	Sta. 151k143-153	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		

											
위치	Sta. 151k123-133	선별	T1	위치	보조	위치	Sta. 151k113-123	선별	T1	위치	TCL
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.2		
											
위치	Sta. 151k103-113	선별	T1	위치	보조	위치	Sta. 151k093-103	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k083-093	선별	T1	위치	보조	위치	Sta. 151k083-093	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		

											
위치	Sta. 151k073-083	선별	T1	위치	보조	위치	Sta. 151k063-073	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k063-073	선별	T1	위치	보조	위치	Sta. 151k053-063	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 0.5/1.0		
											
위치	Sta. 151k053-063	선별	T1	위치	보조	위치	Sta. 151k043-053	선별	T1	위치	보조
내용	균열		Cw= 0.5/1.0			내용	균열		Cw= 2.5/1.0		

											
위치	Sta. 152k103-113	선별	T1	위치	채움	위치	Sta. 151k873-883	선별	T2	위치	TCL
내용	파손		A= 0.1x0.1			내용	침목도상분리		1EA		
											
위치	Sta. 151k873-883	선별	T2	위치	TCL	위치	Sta. 151k863-873	선별	T2	위치	TCL
내용	침목도상분리		1EA			내용	침목도상분리		1EA		
											
위치	Sta. 151k863-873	선별	T2	위치	TCL	위치	Sta. 151k863-873	선별	T2	위치	TCL
내용	침목도상분리		1EA			내용	침목도상분리		1EA		



위치	Sta. 151k643-653	선별	T2	위치	TCL
내용	경계부 균열	Cw= 0.5/2.2 (2EA)			




위치	Sta. 151k643-653	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	Sta. 151k633-643	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	Sta. 151k283-293	선별	T2	위치	보조
내용	균열	Cw= 0.5/0.5			



위치	Sta. 151k153-163	선별	T2	위치	보조
내용	균열	Cw= 0.5/1.0			



위치	Sta. 151k033-043	선별	T2	위치	채움
내용	파손	A= 0.2x0.2			