

18. 죽청터널 토공노반(G75)



위치	Sta. 152k447-457	선별	T1	위치	HSB
내용	균열	Cw=	0.5/1.0		




위치	Sta. 152k437-447	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.4		



위치	Sta. 152k437-447	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.4		



위치	Sta. 152k427-437	선별	T1	위치	HSB
내용	균열	Cw=	0.3/0.3		



위치	Sta. 152k413-427	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.4		



위치	Sta. 152k413-427	선별	T1	위치	TCL
내용	균열	Cw=	0.3/0.4		

											
위치	Sta. 152k413-427	선별	T1	위치	TCL	위치	Sta. 152k413-427	선별	T1	위치	TCL
내용	균열		Cw= 0.3/0.4			내용	균열		Cw= 0.3/0.4		
											
위치	Sta. 152k413-427	선별	T1	위치	TCL	위치	Sta. 152k617-627	선별	T1	위치	TCL
내용	균열		Cw= 0.3/0.4			내용	침묵도상분리		1EA		
											
위치	Sta. 152k617-627	선별	T1	위치	채움	위치	Sta. 152k457-467	선별	T2	위치	TCL
내용	파손		A= 0.2x0.2			내용	침묵도상분리		1EA		