



20. 성덕제1터널 토공노반(G76)



위치	Sta. 153k058-068	선별	T1	위치	TCL
내용	균열		Cw= 0.3/0.4		



위치	Sta. 153k078-088	선별	T1	위치	TCL
내용	균열		Cw= 0.3/0.4		



위치	Sta. 153k048-058	선별	T1	위치	TCL
내용	균열		Cw= 0.3/0.4		



위치	Sta. 153k018-028	선별	T1	위치	TCL
내용	경계부 균열		Cw= 0.1/2.3		



위치	Sta. 153k088-098	선별	T2	위치	TCL
내용	경계부 균열		Cw= 0.1/2.3		



위치	Sta. 153k088-098	선별	T2	위치	TCL
내용	경계부 균열		Cw= 0.1/2.3		