






36. 장산터널 토공노반(G84)


											
위치	STA. 160K343-353	선별	T2	위치	TCL	위치	STA. 160K313-323	선별	T2	위치	TCL
내용	파손		A= 0.1x0.1			내용	균열		Cw= 0.2/0.4		
											
위치	STA. 160K313-323	선별	T1	위치	TCL	위치	STA. 160K383-393	선별	T2	위치	TCL
내용	균열		Cw= 0.2/0.7			내용	균열		Cw= 0.2/0.5		
											
위치	STA. 160K513-523	선별	T1	위치	TCL	위치	STA. 160K453-463	선별	T1	위치	TCL
내용	균열		Cw= 0.2/0.5			내용	침목도상분리		1 EA		



위치	STA. 160K423-433	선별	T2	위치	TCL
내용	균열	Cw= 0.2/0.5			




위치	STA. 160K413-423	선별	T1	위치	TCL
내용	백태	A= 1.0x1.8			



위치	STA. 160K413-423	선별	T1	위치	TCL
내용	침목도상분리	1 EA			



위치	STA. 160K413-423	선별	T1	위치	TCL
내용	침목도상분리	1 EA			



위치	STA. 160K383-393	선별	T1	위치	TCL
내용	균열	Cw= 0.2/0.4			

